
## **LCS-6B Liquid Level Above Quarry Floor**




The transducer became non-operational on 1/13/20. Liquid level was measured manually on 2/21/20.

17413							
174.15	Gara Asseting	Level Balon	Translator Expli- tion Top of Goding	Base of Sump Elevation	Pump on during Teaconstrain?		
	70111	AAA	\$5.5 \$5.5	27.0	- :	Part and Toronto	
100.10	-		101	20.0	-	Delication of the last	
12.3	2001		101	0.0	- 1	Artes I	
100.10	-		101	20.0	-	Delication of the last	
122.15	-		100	50.0		Advert Control	
100.10		40.4	101	20.0	-	Delication of the last	
1913	-	20.1	57.1	60.0		Arrest Terror	the annihold to the so today deal a finite of a finite
100.10	-	***	204 204	90.0	-	Section Control	
192.12	2007	22.5	50.1	20.00	-	kinthan	
100.15		A1.4	901 904	W1.0	÷	Participate Company	
100.40	100.1	***	101	90.9		Refranci Tomas	
100.00	200	40.4	404	90.0	-	Actual Control	
12.3	****	11.	101	0.0	-	Artes I	
100.10	2001 2001	40.4	2014 2014	20.0	-	Sections Section	
100.40	(a))		904 904	20.0		Performan Torontono Performan Torontono	Annual de la contraction de la character de la contracter
LGE. 13	58617		674	20		Sectional Terraturer	Purp of the training law, for shared or fire rate: Purphents
12.3	2001		101	0.0	- 1	Artes I	
100.10	-		204	90.0	÷		
1913	1000		101	60.0	-	- Recorded	
100.10	****		101	20.0	-	Delication of the last	
192.13	2011) 2011)		501	90.00		Participant Commission Participant Commission	
100 10	and the same		201 201			Refrant Tonor	
100.40	-		454	90.9	-	Autorit Tomaton	Pump off formulationance. Pump and terrations whethird to be registered and a highlight.  Pump and terrational terrations whethird to be registered.
100.10	100000		404	90.0		Belows Senten	Pump off for maintenance. Pump and transfers replacement passing and
100.40			454	90.9	-	Autorit Tomaton	Amp of te maintenance. Amp and tenation replacement passing and process of te maintenance. Ame and tenation replacement passing and
100.13			454	90.W		Perfect of Terrorism	Aury of to maintenance Pump and transfers replacement wherein to make distribute.
		<u> </u>	-	90.0			Pump of to maintenance Pump and benefice repleaement selection to Pump of to maintenance Pump and benefice repleaement colored in
100.10	-000		951	90.0		Section 2	Any of terranserana Any and terralize replacement programs of
		<u> </u>	-	90.0			Puny of to naistenana. None and tenderal replacement proported in None of to naistenana. None and tenderal replacement colored in
100.10	-0.00		951	90.0		Section 2	Any of terranserana Any and terralize replacement programs of
		-		90.0	-		Pump of to maintenance. Pump and terrelesconsplacement positional of Pump of to maintenance. Pump and terrelesconsplacement control of
100.10	-5-1		951	90.0		Section 2	Any of terranserana Any and terralize replacement programs of
100.00		_		90.0			Pump of ternalities area. Pump and ternalise replacement selectable to Pump replacement test place the seast of 2 fc/18. Pump replacement test place the seast of 2 fc/18. Pump replacement test place the
105.10	21435		104	20.0	-	Settings Supplier	Annual of the second states of
100.43	22.22		404 404	20.0		Performance Communication	Annual An
176.15	17414		97.5 97.5	90.0		Federal Section	
100.43	****		404 404	90.00 90.00		Antonia Senten	
100.10	feet.		453	90.90		Belows Tondon	Purp replacement attempted the season of 100 M for the conceptual of
100.40	F4444		404	363.30		Sectional Section	Any specimens and place better 1800 to an arrange
100.10	65533		453	90.90		Belows Tondon	Purp replacement attempted the season of 100 M for the conceptual of
100.40			404	363.30		Sectional Section	Any appearance of the second o
100.10			453	90.90		Belows Tondon	Educator pump installation main places on 6.53.54. Pump applications active  Course course inspectation main places on 6.53.54. Pump applications active  Course course inspectation main places on 6.53.54. Pump applications active  Course course inspectation main places on 6.53.54. Pump applications active  Course course inspectation main places on 6.53.54. Pump applications active  Course course inspectation main places on 6.53.54. Pump application active  Course course inspectation main places on 6.53.54. Pump application active  Course course inspectation main places on 6.53.54. Pump application active  Course course inspectation main places on 6.53.54. Pump application active  Course course course inspectation main places on 6.53.54. Pump application active  Course
100.40	*****		404	363.30		Sectional Section	Carrier and Transaction States and Control Property Life Spinish
100.10	200		453	90.90		Belows Tondon	Salara yang hadiatan sakyias an 81218. Pany dang ani syinta Salara salara nagingan sakajas an 81218. Pany dang ani apini
100.40	2000		404	363.30		Sectional Section	Facine pump manufact and State on ATTA Pump samp and option
100.10	15534		453	90.90		Belows Tondon	Salara yang hadiatan sakyias an 81218. Pany dang ani syinta Salara salara nagingan sakajas an 81218. Pany dang ani apini
100.40	****		404	363.30		Sectional Section	Facine pump manufact and State on ATTA Pump samp and option
100.10			453	90.90		Belows Tondon	Salara yang hadiatan sakyias an 81218. Pany dang ani syinta Salara salara nagingan sakajas an 81218. Pany dang ani apini
100.40	*****		404	363.30		Sectional Section	Facine pump manufact and State on ATTA Pump samp and option
100.10	200		453	90.90		Belows Tondon	Salara yang hadiatan sakyias an 81218. Pany dang ani syinta Salara salara nagingan sakajas an 81218. Pany dang ani apini
100.40	*****		201	90.0		Belowed Terretory	Educate pump institution tests place on 61216. Autop darlage and optimize
100.10	1500		453	90.90		Belows Tondon	Salara yang hadiatan sakyias an 81218. Pany dang ani syinta Salara salara nagingan sakajas an 81218. Pany dang ani apini
100.40	*****		404	363.30		Sectional Section	Facine pump manufact and State on ATTA Pump samp and option
100.40	-		454	90.9	-	Autorit Tomaton	Educar pump indefesion test place on \$1218. Pump damap and opinion damap pump indefesion test place on \$1218. Pump damap and opinion
100.10			404	90.0		Belows Senten	Educar yang indulation testificial on \$1712 Pump darkap and options
100.40			454	90.9	-	Autorit Tomaton	Educar pump indefesion test place on \$1218. Pump damap and opinion damap pump indefesion test place on \$1218. Pump damap and opinion
100.10			404	90.0		Belows Senten	Educar yang indulation testificial on \$1712 Pump darkap and options
100.40			454	90.9	-	Autorit Tomaton	Educar pump indefesion test place on \$1218. Pump damap and opinion damap pump indefesion test place on \$1218. Pump damap and opinion
100.10	-20234		404	90.0		Belows Senten	Educar yang indulation testificial on \$1712 Pump darkap and options
100.10	100111		453	90.0	-	No.	Facility pump residents restricted in \$1710 horsy strong and option
100.10	-004		404	90.0		Belows Senten	Educar yang indulation testificial on \$1712 Pump darkap and options
100.40				90.9	-	Section Construction	Educate pump industrialism tests place on 6 h 2 ht. Pump dartup and optimise
100.10			453				Educate pump inductation tests place on \$1218. Pump darkep and optimise
	(90)		974 974	90.0		Defendance	Share yang indebutor sali yang at 61 218. Pany dang yan apinia Share yang indebutor sali yang at 61 218. Pany dang yan apinia
100.40			#04 #04	W W	Н	Parlicular Securition Parlicular Securition	Saure pump materian minjake of 6-248 Pump away are optime Saure pump materian minjake of 6-248 Pump away are optime Saure pump materian minjake of 6-248 Pump away are optime Saure pump materian minjake of 6-248 Pump away are optime Saure pump materian minjake of 6-248 Pump away are optime
100.10	2000 2000 2000 2000 2000		904 904 904 904	***	÷	horas la como	After a pump rediction real pain of \$1.545. Area passing and specific distinct pump rediction real pains of \$1.545. Area passing and specific distinct pump redictions real pains of \$1.545. Area passing and option distinct pump redictions real pains of \$1.545. Area passing and option distinct pump redictions real pains of \$1.545. Area passing and option distinct pump redictions real passing as of \$1.545. Area passing and option
100.10	2000 2000 2000 2000 2000 2000		200 200 200 200 200 200 200 200 200 200	20 M		Prince Services	Among pung membenan mangawa an NAMA Ang pamag ana santan Manang pung pembenan ang pama an NAMA Pang pangga an apam Manang pung membenan mangawa an NAMA Ang pangga panggan Manang pung pembenan mangawa an NAMA Pang panggan ang apam Manang pung pembenan mangawa an NAMA Ang panggan an apam Manang pung pembenan mangawa an NAMA Pang panggan an apam Manang pung pembenan mangawa an NAMA Pang panggan an apam Manang pung pembenan mangawa an NAMA Pang panggan an apam Manang pung pembenan mangawa an NAMA Pang panggan ang apam Manang pung pembenan mangawa an NAMA Pang panggan an apam
(M A)			201 201 201 201 201 201 201 201	90 W			Among pung managan mangan and SASA dang amang mengangan pengangan ang ang ang ang ang ang ang ang
100 10 100 10 100 10 100 10 100 10	2000 2000 2000 2000 2000 2000 2000 200		2014 2014 2015 2015 2015 2016 2016 2016 2016 2016 2016 2016 2016	20 M		house bearing	Among pung manahan mangan and SASA dang anang and mangan and manga
100.40	MANA MANA MANA MANA MANA MANA MANA MANA		201 201 201 201 201 201 201 201 201 201	200		Acceptance of the control of the con	
	2011 2011 2011 2011 2011 2011 2011 2011		201 201 201 201 201 201 201 201 201 201	90 W 90 W 90 W 90 W 90 W 90 W 90 W		hours and hours	
100 to 10	200 A 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		2014 2015 2015 2015 2016 2016 2016 2016 2016 2016 2016 2016	90 0 90 0 90 0 90 0 90 0 90 0 90 0 90 0		briefless	
100 to 10	2000 2000 2000 2000 2000 2000 2000 200		2013 2013 2013 2013 2013 2013 2013 2013	90 0 90 0 90 0 90 0 90 0 90 0 90 0 90 0		briefly	
100 to 10	2011 2011 2011 2011 2011 2011 2011 2011		2014 2015 2014 2014 2015 2015 2015 2015 2015 2015 2015 2015	90 90 90 90 90 90 90 90 90 90 90 90 90 9		Security Sec	
100 to 10	2011 2011 2011 2011 2011 2011 2011 2011		100 100 100 100 100 100 100 100 100 100	900 900 900 900 900 900 900 900 900 900		Security Sec	
100 A	2011 2011 2011 2011 2011 2011 2011 2011		100 100 100 100 100 100 100 100 100 100	903 903 903 903 903 903 903 903 903 903		ACCUMULATION OF THE PROPERTY O	
100 A3 10	201111 20111 2011 2011 2011 20111 20111 2011 20111 20111 2011 20111 20111 20111 20111 2011 20111 20111 20111		100 100 100 100 100 100 100 100 100 100	90.5 90.5 90.5 90.5 90.5 90.5 90.5 90.5			
100 A3 10	2011 2012 2013 2013 2013 2013 2013 2013		100 100 100 100 100 100 100 100 100 100	903 903 903 903 903 903 903 903 903 903			
100 to 10	2011 2011 2011 2011 2011 2011 2011 2011		## ## ## ## ## ## ## ## ## ## ## ## ##	90 % 90 % 90 % 90 % 90 % 90 % 90 % 90 %			
100 A) A) 100 A) A) 100 A)	2011 2011 2011 2011 2011 2011 2011 2011		10	90 5 90 5 90 5 90 5 90 5 90 5 90 5 90 5			
100 A3 10			10	90.5 90.5 90.5 90.5 90.5 90.5 90.5 90.5			
100 A3 10	2010 2010 2010 2010 2010 2010 2010 2010			90.5 90.5			
100 A) 10				90.00 90			
100 A) A) 100 A) A) 100 A) A) 100 A)				90.0 90.0			
100 A) A) 100 A) A) 100 A) A) A) 100 A)	1000 1000 1000 1000 1000 1000 1000 100			201 201 201 201 201 201 201 201 201 201			
100 A) A) 100 A) A) 100 A)				201			
				201 201 201 201 201 201 201 201 201 201			
				201			

CGS-2D   2782919   NA		Date	Measured Liquid	Transducer Height	Base of Sump	Elevation of	Pump on during		
LCS Number   Collected   Tarreducer (FL)   Clearry (FL)   (FL MSL)   (FL MSL)   (FL MSL)   (FN MSL)   (FL MS		Reading	Level Above	above Floor of	Elevation	Leachate	measurement?		
CS-27   2207/19 N/A	LCS Number		Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)		(Y/N)	Liquid level meter used	Comments
CS-20   278/19   N/A			N/A			,			PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-20	LCS- 2D	2/28/19	N/A	14.4			N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-20   322/19   N/A		3/7/19	N/A	14.4			N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-20   3/22/19   N/A	LCS- 2D	3/15/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
CIS-20   39/29/19   N/A									PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-20			N/A				N		PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-20	LCS- 2D	4/5/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-20	LCS- 2D	4/12/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-2D			N/A				N		PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-2D	LCS- 2D	4/26/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D   S716/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S724/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S731/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S741/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S741/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S767/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S767/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   T4.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   T4.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   T4.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   T767/19   N/A   T4.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S767/19   N/A   T4.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace   LCS- 2D   S767/19   N/A   T4.4   2	LCS- 2D	5/3/19	N/A	14.4			N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LGS-2D   563/19	LCS- 2D	5/10/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LGS-2D   56/31/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   67/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   67/41/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   67/21/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   67/21/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   77/61/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   77/61/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   77/61/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   77/61/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   77/61/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   77/61/9   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   80/719   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   80/719   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   80/719   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   97/719   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D   97/719   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to	LCS- 2D	5/15/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D   53/119   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   67/149   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   67/149   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   67/249   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   67/249   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   77/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   87/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   87/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   97/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £2 BGS, failed stator, needs replace LCS-2D   97/549   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of £	LCS- 2D	5/24/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
CGS-2D 6/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 6/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 7/51/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 7/51/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 7/51/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 7/52/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 7/52/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 8/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 9/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 9/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 9/21/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LGS-2D 9/21/19 N/A 14.4 235.92 N Dedicated Transducer P	LCS- 2D	5/31/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LGS-2D 6/28/19	LCS- 2D	6/7/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 75/19 N/A	LCS- 2D	6/14/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LGS-2D 77/19 N/A	LCS- 2D	6/21/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D	LCS- 2D	6/28/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 77/18/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 77/26/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 87/219 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 87/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 87/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 87/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 87/23/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 87/23/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 98/79 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 98/79 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 99/2019 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 99/2019 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 99/2019 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 99/2019 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/1419 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/1419 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/1419 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/1419 N/A 14.4 235.92 N Dedicated Transducer PCP Inst	LCS- 2D	7/5/19	N/A	14.4			N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 7/18/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/2/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/2/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/19/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/19/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 8/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 9/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 9/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 9/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 9/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 9/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/4/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/4/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/4/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 10/14/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62 BGS, failed stator, needs replace LCS-2D 11/14/19 N/A 14.4 235.92 N Dedicated Transducer PCP	LCS- 2D	7/12/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 8/9/19	LCS- 2D	7/18/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 8/16/19 N/A	LCS- 2D	7/25/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 8/16/19 N/A	LCS- 2D	8/2/19	N/A	14.4			N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D		8/9/19	N/A	14.4			N		PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D	LCS- 2D	8/16/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D   8/30/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/6/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/13/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/20/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/27/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/4/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/11/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/11/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/13/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/15/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/15/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/27/19   N/A	LCS- 2D	8/23/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D   9/3/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/27/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/27/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/4/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/11/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/19/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/29/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/6/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/6/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/6/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/20/19   N/A   14.4	LCS- 2D	8/30/19	N/A	14.4	235.92		N		PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D   9/20/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   9/27/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/41/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/11/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   10/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/1/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/1/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/1/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/15/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/29/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   11/29/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/26/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/26/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   12/20/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS-2D   1/3/20   N/A	LCS- 2D	9/6/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D   9/27/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   10/4/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   10/11/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   10/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   10/25/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   11/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   11/8/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   11/18/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   11/19/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   11/19/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   12/6/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   12/6/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   12/20/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   12/20/19   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   1/3/20   N/A   14.4   235.92   N   Dedicated Transducer   PCP Installed to depth of 62' BGS, failed stator, needs replace   LCS- 2D   1	LCS- 2D	9/13/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	LCS- 2D	9/20/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 10/11/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 10/18/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 10/25/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/11/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/16/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/16/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/26/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/	LCS- 2D	9/27/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS-2D 10/18/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 10/25/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 11/11/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 11/8/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 11/29/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 11/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 1/20/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 1/21/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS-2D 1/21/20 N/A 14.4 235.92	LCS- 2D	10/4/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 10/25/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/16/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/29/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/66/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17	LCS- 2D	10/11/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 11/1/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/18/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/29/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/120 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/120 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/12	LCS- 2D	10/18/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 11/1/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/18/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/29/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/120 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/120 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/120 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/13/1	LCS- 2D	10/25/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 11/15/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/29/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 13/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 11/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A	LCS- 2D	11/1/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 11/29/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/6/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace		11/8/19	N/A	14.4			N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 12/3/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235				14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/12/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.		11/29/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 12/13/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/20/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/12/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.	LCS- 2D	12/6/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace	LCS- 2D	12/13/19		14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 12/27/19 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/3/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace	LCS- 2D	12/20/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace PCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace	LCS- 2D	12/27/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 1/10/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace PCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace			N/A	14.4			N		PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 1/17/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/24/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace PCP Installed to depth of 62' BGS,		1/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 1/31/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace	LCS- 2D	1/17/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace	LCS- 2D	1/24/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D 2/7/20 N/A 14.4 235.92 N Dedicated Transducer PCP Installed to depth of 62' BGS, failed stator, needs replace	LCS- 2D	1/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
									PCP Installed to depth of 62' BGS, failed stator, needs replacement
	LCS- 2D	2/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
			N/A	14.4			N		PCP Installed to depth of 62' BGS, failed stator, needs replacement


				\A/-!! T-4-! D4-				
	Data	Magazinad Liquid	Transducer Denth	Well Total Depth	Claustian of	Duman on during		
	Date	Measured Liquid	Transducer Depth	from Top of	Elevation of	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Casing (Ft.)	Leachate	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS-3D	2/20/19	33.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/28/19	35.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/7/19	31.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/15/19	33.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/22/19	36.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/29/19	36.0	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/5/19	36.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/12/19	36.5	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/19/19	35.9	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/26/19	36.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/3/19	35.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/10/19	35.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/15/19	34.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/24/19	35.3	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/31/19	37.5	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/7/19	39.0	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/14/19	39.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/21/19	39.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/28/19	39.6	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/5/19	39.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/12/19	36.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/18/19	36.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/25/19	37.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/2/19	37.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/9/19	34.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/16/19	34.2	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/23/19	34.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/30/19	32.9	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/6/19	32.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/13/19	32.5	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/20/19	35.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/27/19	37.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/4/19	42.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/11/19	43.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/18/19	44.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/25/19	48.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/1/19	49.5	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/8/19	51.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/15/19	52.0	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/22/19	52.1	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/27/19	51.0	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/6/19	52.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/0/19	51.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/20/19	52.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/27/19	51.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/3/20	49.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/10/20	49.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/17/20	46.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/17/20	40.4	N/A N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/24/20	41.0	N/A N/A	140		Y	Heron Dipper T	Pump operational, liquid level measured manually  Pump operational; liquid level measured manually
LCS-3D LCS-3D	2/7/20	41.2	N/A N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually  Pump operational; liquid level measured manually
LCS-3D LCS-3D	2/14/20	43.6 47.4	N/A N/A	140		Y		
LCS-3D LCS-3D						Y	Heron Dipper T	Pump operational; liquid level measured manually
TC2-3D	2/21/20	48.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually

## LCS-3D Liquid Level Below Ground Surface




	Date	Measured Liquid	Transducer Depth	Base of Sump	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Elevation	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 4B	2/20/19	74.0	81.0	244.00	(1/N) V	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/28/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	3/7/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/15/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	3/22/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	3/29/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/5/19	74.0	81.0	244.00	Ϋ́	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/12/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/19/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/26/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/3/19	74.0	81.0	244.00	Ϋ́	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/10/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/15/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/24/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/31/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/7/19	74.0	81.0	244.00	Ϋ́	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/14/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/21/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/28/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/5/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/12/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	7/18/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	7/10/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	8/2/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/9/19	74.0	81.0	244.00	Y	Dedicated Transducer  Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/16/19	74.0	81.0	244.00	Ÿ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/23/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/30/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/6/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/13/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/20/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/27/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/4/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/11/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/18/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/25/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/1/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/8/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/15/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/22/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/29/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/6/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/13/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/20/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/27/19	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/3/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/17/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/24/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/31/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/14/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/21/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS

## LCS-4B Liquid Level Below Ground Surface



1			1		1				T
	Date	Measured Liquid	Transducer Height	Base of Sump		Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Elevation	Height of	Leachate	measurement?		
LCS Number	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	Liquid (ft )	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 5B	2/20/19	12.9	21.9	235.3	34.8	270.10	Υ	Dedicated Transducer	
LCS- 5B	2/27/19	12.2	21.9	235.3	34.1	269.40	Υ	Dedicated Transducer	
LCS- 5B	3/6/19	11.8	21.9	235.3	33.7	269.00	Υ	Dedicated Transducer	
LCS- 5B	3/15/19	13.2	21.9	235.3	35.1	270.40	Υ	Dedicated Transducer	
LCS- 5B	3/22/19	12.6	21.9	235.3	34.5	269.80	Υ	Dedicated Transducer	
LCS- 5B	3/29/19	13.6	21.9	235.3	35.5	270.80	Υ	Dedicated Transducer	
LCS- 5B	4/4/19	12.1	21.9	235.3	34.0	269.30	Υ	Dedicated Transducer	
LCS- 5B	4/12/19	13.0	21.9	235.3	34.9	270.20	Y	Dedicated Transducer	
LCS- 5B	4/19/19	12.2	21.9	235.3	34.1	269.40	Υ	Dedicated Transducer	
LCS- 5B	4/26/19	12.5	21.9	235.3	34.4	269.70	Y	Dedicated Transducer	
									B 1 1/1 // E/1/10 B
									Pump was observed to be non-operational on 5/1/19. Pump was
LCS- 5B	5/3/19	13.3	21.9	235.3	35.2	270.50	Y	Dedicated Transducer	replaced on 5/3/19
LCS- 5B	5/10/19	11.6	21.9	235.3	33.5	268.80	Y	Dedicated Transducer	
LCS- 5B	5/15/19	11.9	21.9	235.3	33.8	269.10	Υ	Dedicated Transducer	
LCS- 5B	5/24/19	13.1	21.9	235.3	35.0	270.30	Υ	Dedicated Transducer	
LCS- 5B	5/31/19	11.6	21.9	235.3	33.5	268.80	Υ	Dedicated Transducer	
LCS- 5B	6/7/19	12.7	21.9	235.3	34.6	269.90	Υ	Dedicated Transducer	
LCS- 5B	6/14/19	12.7	21.9	235.3	34.6	269.90	Υ	Dedicated Transducer	
LCS- 5B	6/21/19	11.7	21.9	235.3	33.6	268.90	Υ	Dedicated Transducer	
LCS- 5B	6/28/19	13.2	21.9	235.3	35.1	270.40	Y	Dedicated Transducer	
LCS- 5B	7/5/19	12.2	21.9	235.3	34.1	269.40	Υ	Dedicated Transducer	
LCS- 5B	7/12/19	13.4	21.9	235.3	35.3	270.60	Υ	Dedicated Transducer	
LCS- 5B	7/18/19	11.6	21.9	235.3	33.5	268.80	Υ	Dedicated Transducer	
LCS- 5B	7/25/19	12.8	21.9	235.3	34.7	270.00	Υ	Dedicated Transducer	
LCS- 5B	8/2/19	13.5	21.9	235.3	35.4	270.70	Υ	Dedicated Transducer	
LCS- 5B	8/9/19	11.3	21.9	235.3	33.2	268.50	Υ	Dedicated Transducer	
LCS- 5B	8/16/19	12.6	21.9	235.3	34.5	269.80	Υ	Dedicated Transducer	
LCS- 5B	8/23/19	12.5	21.9	235.3	34.4	269.70	Υ	Dedicated Transducer	
LCS- 5B	8/30/19	12.3	21.9	235.3	34.2	269.50	Υ	Dedicated Transducer	
LCS- 5B	9/6/19	11.1	21.9	235.3	33.0	268.30	Υ	Dedicated Transducer	
LCS- 5B	9/13/19	12.6	21.9	235.3	34.5	269.80	Υ	Dedicated Transducer	
LCS- 5B	9/20/19	12.8	21.9	235.3	34.7	270.00	Υ	Dedicated Transducer	
LCS- 5B	9/27/19	13.0	21.9	235.3	34.9	270.20	Υ	Dedicated Transducer	
LCS- 5B	10/4/19	12.2	21.9	235.3	34.1	269.40	Υ	Dedicated Transducer	
LCS- 5B	10/11/19	13.3	21.9	235.3	35.2	270.50	Υ	Dedicated Transducer	
LCS- 5B	10/18/19	11.5	21.9	235.3	33.4	268.70	Υ	Dedicated Transducer	
LCS- 5B	10/25/19	12.7	21.9	235.3	34.6	269.90	Υ	Dedicated Transducer	
LCS- 5B	11/1/19	12.3	21.9	235.3	34.2	269.50	Υ	Dedicated Transducer	
LCS- 5B	11/8/19		21.9	235.3		235.30	N	Dedicated Transducer	The transducer was observed to be non-operational on 11/6/19.  Transducer replacement is scheduled on 11/13/19.
			i		İ	1			The transducer was observed to be non-operational on 11/6/19
			]		Ì	I			and was replaced on 11/13/19. After transducer replacement,
									pump was non-operational due to suspected frozen forcemain
LCS- 5B	11/15/19		21.9	235.3		235.30	N	Dedicated Transducer	section. Troubleshooting will continue the week of 11/18/19.
									The transducer was observed to be non-operational on 11/6/19
									and was replaced on 11/13/19. After transducer replacement,
									pump was non-operational due to suspected frozen forcemain
						1			section. The pump and motor were replaced on 11/19/19 and
LCS- 5B	11/22/19	11.7	21.9	235.3	33.6	268.90	Υ	Dedicated Transducer	LCS-5B became fully operational.
LCS- 5B	11/22/19	11.7	21.9	235.3	32.9	268.20	Y	Dedicated Transducer	200-00 became fully operational.
LCS- 5B	12/6/19	12.4	21.9	235.3	34.3	269.60	Y	Dedicated Transducer	
LCS- 5B	12/0/19	12.4	21.9	235.3	33.9	269.20	Y	Dedicated Transducer	<u> </u>
LCS- 5B	12/13/19	13.1	21.9	235.3	35.0	270.30	Y	Dedicated Transducer	
LCS- 5B	12/20/19	10.0	21.9	235.3	31.9	267.20	Y	Dedicated Transducer	
LCS- 5B	1/3/20	11.3	21.9	235.3	33.2	268.50	Y	Dedicated Transducer	
LCS- 5B	1/10/20	12.4	21.9	235.3	34.3	269.60	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B LCS- 5B	1/10/20	12.4	21.9	235.3	34.3	269.60	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B LCS- 5B	1/1//20	13.0	21.9	235.3	34.9	270.20	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B LCS- 5B	1/24/20	13.0	21.9	235.3	34.9	268.90	Y	Dedicated Transducer  Dedicated Transducer	
	2/7/20	11.7	21.9		33.6	269.80	Y		
LCS- 5B				235.3				Dedicated Transducer	
LCS- 5B LCS- 5B	2/14/20	12.3	21.9 21.9	235.3	34.2	269.50	Y	Dedicated Transducer	
11>= 5B	2/21/20	11.3	∠1.9	235.3	33.2	268.50	Υ	Dedicated Transducer	

## LCS-5B Liquid Level Above Quarry Floor



<sup>\*</sup>The transducer in LCS-5B was down from 11/6/19 to 11/19/19.

	Date		Transducer Height	Base of Sump		Elevation of	Pump on during		
	Reading		above Floor of	Elevation	Height of	Leachate	measurement?		
LCS Number	Collected	V	Quarry (Ft.)	(Ft. MSL)	Liquid (ft )	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 6B	2/20/19	8.9	9.4	429.52	18.3	447.82	Y	Dedicated Transducer	
LCS- 6B	2/28/19	9.0	9.4	429.52	18.4	447.92	Y	Dedicated Transducer	
LCS- 6B	3/7/19	9.6	9.4	429.52	19.0	448.52	Y	Dedicated Transducer	
LCS- 6B	3/15/19	9.2	9.4	429.52	18.6	448.12	Y	Dedicated Transducer	
LCS- 6B	3/22/19	9.5	9.4	429.52	18.9	448.42	Y	Dedicated Transducer	
LCS- 6B	3/29/19	9.8	9.4	429.52	19.2	448.72	Υ	Dedicated Transducer	
LCS- 6B	4/5/19	9.0	9.4	429.52	18.4	447.92	Y	Dedicated Transducer	
LCS- 6B	4/12/19	9.6	9.4	429.52	19.0	448.52	Y	Dedicated Transducer	
LCS- 6B	4/19/19	9.9	9.4	429.52	19.3	448.82	Y	Dedicated Transducer	
LCS- 6B	4/26/19	9.5	9.4	429.52	18.9	448.42	Y	Dedicated Transducer	
LCS- 6B	5/3/19	9.1	9.4	429.52	18.5	448.02	Y	Dedicated Transducer	
LCS- 6B	5/10/19	10.0	9.4	429.52	19.4	448.92	Y	Dedicated Transducer	
LCS- 6B	5/15/19	9.8	9.4	429.52	19.2	448.72	Y	Dedicated Transducer	
LCS- 6B	5/24/19	9.7	9.4	429.52	19.1	448.62	Y	Dedicated Transducer	
LCS- 6B	5/31/19	10.1	9.4	429.52	19.5	449.02	Y	Dedicated Transducer	
LCS- 6B	6/7/19	10.4	9.4	429.52	19.8	449.32	Y	Dedicated Transducer	
LCS- 6B	6/14/19	10.2	9.4	429.52	19.6	449.12	Y	Dedicated Transducer	
LCS- 6B	6/21/19	9.6	9.4	429.52	19.0	448.52	Y	Dedicated Transducer	
LCS- 6B LCS- 6B	6/28/19 7/5/19	10.0 9.4	9.4 9.4	429.52 429.52	19.4 18.8	448.92 448.32	Y	Dedicated Transducer	
LCS- 6B	7/12/19	10.3	9.4	429.52	19.7	448.32	Y	Dedicated Transducer Dedicated Transducer	
LCS- 6B	7/12/19	9.7	9.4	429.52	19.7	449.22	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 6B	7/16/19	9.3	9.4	429.52	18.7	448.22	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 6B	8/2/19	9.0	9.4	429.52	18.4	447.92	Y	Dedicated Transducer	
LCS- 6B	8/9/19	10.7	9.4	429.52	20.1	449.62	Y	Dedicated Transducer	
LCS- 6B	8/16/19	9.9	9.4	429.52	19.3	448.82	Y	Dedicated Transducer	
LCS- 6B	8/23/19	10.2	9.4	429.52	19.6	449.12	Ÿ	Dedicated Transducer	
LCS- 6B	8/30/19	8.8	9.4	429.52	18.2	447.72	Ý	Dedicated Transducer	
LCS- 6B	9/6/19	9.5	9.4	429.52	18.9	448.42	Y	Dedicated Transducer	
LCS- 6B	9/13/19	10.5	9.4	429.52	19.9	449.42	Ÿ	Dedicated Transducer	
LCS- 6B	9/20/19	10.1	9.4	429.52	19.5	449.02	Ý	Dedicated Transducer	
LCS- 6B	9/27/19	9.7	9.4	429.52	19.1	448.62	Y	Dedicated Transducer	
LCS- 6B	10/4/19	9.9	9.4	429.52	19.3	448.82	Ý	Dedicated Transducer	
LCS- 6B	10/11/19	9.4	9.4	429.52	18.8	448.32	Ý	Dedicated Transducer	
LCS- 6B	10/18/19	10.0	9.4	429.52	19.4	448.92	Υ	Dedicated Transducer	
LCS- 6B	10/25/19	9.7	9.4	429.52	19.1	448.62	Y	Dedicated Transducer	
LCS- 6B	11/1/19	10.1	9.4	429.52	19.5	449.02	Y	Dedicated Transducer	
LCS- 6B	11/8/19	9.9	9.4	429.52	19.3	448.82	Υ	Dedicated Transducer	
LCS- 6B	11/15/19	9.5	9.4	429.52	18.9	448.42	Υ	Dedicated Transducer	
LCS- 6B	11/22/19	9.8	9.4	429.52	19.2	448.72	Υ	Dedicated Transducer	
LCS- 6B	11/29/19	8.9	9.4	429.52	18.3	447.82	Y	Dedicated Transducer	
LCS- 6B	12/6/19	10.4	9.4	429.52	19.8	449.32	Y	Dedicated Transducer	
LCS- 6B	12/13/19	10.2	9.4	429.52	19.6	449.12	Y	Dedicated Transducer	
LCS- 6B	12/20/19	9.1	9.4	429.52	18.5	448.02	Y	Dedicated Transducer	
LCS- 6B	12/27/19	9.3	9.4	429.52	18.7	448.22	Y	Dedicated Transducer	
LCS- 6B	1/3/20	10.1	9.4	429.52	19.5	449.02	Y	Dedicated Transducer	
LCS- 6B	1/10/20	9.2	9.4	429.52	18.6	448.12	Y	Dedicated Transducer	
									The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS- 6B	1/17/20		9.4	429.52			N	Dedicated Transducer	is pending replacement parts arrival.
	l		[						The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS- 6B	1/24/20		9.4	429.52			N	Dedicated Transducer	is pending replacement parts arrival.
			I						The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS- 6B	1/31/20		9.4	429.52		ļ	N	Dedicated Transducer	is pending replacement parts arrival.
			I						The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS- 6B	2/7/20		9.4	429.52			N	Dedicated Transducer	is pending replacement parts arrival.
			.						The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS- 6B	2/14/20		9.4	429.52			N	Dedicated Transducer	is pending replacement parts arrival.
			l I						The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS- 6B	2/21/20	N/A	N/A	429.52	27.8	457.32	N	Heron Dipper T	is pending replacement parts arrival. Liquid level was measured manually.