dnr.mo.gov

DNR Field Observations

May 23, 2013

Republic Services completed work on SC-4, which is the second of the six RCPs to be abandoned and installed perimeter collection sumps 5, 6, 7, 8 and 13. Two sections of the reinforced concrete pipe were removed from SC-4. As expected with this RCP and the prevailing wind direction, odors were very strong on the east side of the landfill and intermittently noticeable on the south side of the landfill.

Photos of work activity to abandon SC-4.

































