
	15	State of the latest and the latest a	Transfer Teph. Son Teaching	Result Plants Products	12227		
Ë	Ē				Ė		
	П		-	Ш	Н	-	
i	I		i	H	ť		
ı		I		Ш	Н		
	Ш	Ш		Ш	Ш		
	Ш	-	-	Ш	Н	-	
	Ш				Н		
H	Ш	н		М	H		
	Ш				Ш		
	ı	H		Н	1		
Ħ	Ш	Н		Н	т		
10.7	ä	I	ä	ä	1	NAME OF THE OWNER.	
100.00	w		974	-	4	Named Tarable	ten distribute del arma del der arte former depleature
	П	I		Ш	Ш		
			-	Ш	Н		
	Ш			Ш	Ш		
	Ш		Н	Ш	₩		
					Н		Tay of the contract of the second sec
	Н			Н	Н		top fits restricted to participate a today is to appoint
	-			Н	Н		Copella carriera la participa aparectarina e carriera.  Accordina del carriera la participa de carriera de carrier
	П		-	-	-		
			-	-	-		his fit serious has an easter special popular and
10.0	week		- 10	-	1	NAME AND ADDRESS OF	they are not to be an extended a particular for the same for the same for the same and the same same same same same same same sam
MA N	707		90	NV NV	1	Separation of the Control of the Con	Ang Ph. Services Frequent Service Spinore Springer Services Ang Ph. Services Frequent Service Springer Services
ī	Ħ		ŝ	ı	1	Name Tools	Top PC Services Popular Service Special popular Services
	Н		-	-	-		The second registration of the second registrati
10.3	8		81	88	,	Mechan	
	Ĕ			ø	Ħ		
=			=	E			
MAN.	NO.		99	ALC:		handon.	Top-special deposits and the Event accounts
105 W	100		97 94	27	Е	tenertone tenertone	Top opening Reports and Part I has accommoded from the common and the common accommoded to the c
E	E		E	E	Ε		the special dispersion of APP I are assumed.  The special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that  APP I are a special dispersion of Texture assumed that a special dispersion of Texture as a special dispersio
	Е		Ξ	Ξ	Ξ		THE PERSON NAMED IN COLUMN TWO
E	Ε			Ε	Ε		Married with the service of the service of the
E	E	E	Ξ	E	E		Mark you window service of the frequency of the
100 W	-		99	200	Ξ	NAME TANKS	Married State of the State of t
MAX.	100		90	AN AN		Telephone Telephone	Maria party marian series and the Property of the State o
	П				ł		Mark you within those of the forest parties and the forest parties a
	ı				ł		Share you was an experience of the party of
	П						Note you washe to be a street from the property of the section of
	П			Н	ŀ		the part with the second of the following of the
103.3	100		977	200	٠,	NAME TO AN	Allegan and the second
15.7	10		97	20	1	Separation of the Person of th	
100.00	10			1	1	Name To Add	And you was a sound of the forest party of
	Н		H	Н	Н		Acres and the second second
	Н			Н	Н		Mark you within to you will be found to provide the
-	Н				1		And his many related by the principles in the
US N	8 8		90	200		Separation of the Control of the Con	Mark you within house and the foreign open product Mark you within house and the foreign open product the same of the same of
15.5	11		8 8	ł	'n	Section Section	Mark party stated company of the Programmy of product of the decrease of the Programmy of the decrease of decrease of the decrease of the decrease of the decrease of decrease of decre
ĺ	Н		l	l	ľ	-	Mark yang salahin salahin salahin Propertyan disalah Mark yang salahin salahin salahin Propertyan disalah Mark yang salahin salahin salahin salahin
l	Н		l	l	ľ	-	Mark you without suppose of the Post of the participation of the State
	П				ł		Mark you within the second of the forest party of the second of the seco
	ı				ł		Mark you within the second of the forest party of the second of the seco
105.00	8 8		90	82	•	Separation of the Separation o	Mark you within those of the forest party and
105.00	8 10		97	82	•	Separation of the Separation o	Mark you within those of the forest party and
105.3	8		97	-		NAME AND ADDRESS OF	Allegan and the second
	П						Act por many region of the control o
	Н			Н	ŀ		Mark you work to be a first for the party of the last
	Н			Н	ŀ		the part with the second of the following of the
10.7	10		90	-	1	NAME TO AN	Mark you within sures of the forest specialists.
103.3	8 8		977	200	٠,	NAME TO AN	Allegan and the second
100.0	1			1	1	Name To Add	And you was a sound of the forest party of
	Н			Н	ŀ		And you was a state of the party of the part
	F		=	=	Ė		Mark you within to you will be a property of the
==	F			=	=		Mark you within super column by the column of the column o
	-		-	-	÷	Name Toronto	
10.0	1		i	ı	ť	total total	And you was a superior to be a superior of
10.7	-		-		÷	NAME AND ADDRESS OF	
-	Е		E	=	Ė	_	Mark you with the same of the
Œ	Е		E	E	Е		Name and Address of the Owner, where
Ξ	Ē	Ē	Ξ	Ē	Ē		Markey with the service of the free beauty of the service of the s
10.3	É	E	-	Ē	Ε	nancone.	Mark you within the control of the c
10.0	1	Ξ	W/	-	1	NAME TO AN	Manager with the service of the serv
10.0	Ε		- 10		Ξ	NAME AND ADDRESS OF	Mark you with the same of the free beauty and
	E						Mark you with the second of th
	E						Married with Supplication Control and
==	E			=	=		Mark you will be a supplied to the supplied of the supplied to
10.0			-	=	-	NAME TO AN	
10.0	ē		97	=	÷	Mariotal Mariotal	NAME AND ADDRESS OF THE PARTY O
10.0			100		÷	haterholes haterholes	
	F		=	=	Ė		Mark you work to pay 100 to 10
-	F		=	Ξ	F	_	Married week region and frequency and
E	Е		E	Е	Е		Married with representative between the second
	-		-	-	=	Terror	
MAT.	-		10	200	÷	Separate Contract	
10.7			-		÷	NAME AND ADDRESS OF	
E	Е		E	Е	Е		Mark you with the second first frequency of the second sec
-	Е		E	=	Ė	_	Maryon week regarded from the second
E	Е		E	Е	Е		Married with representative between the second
100.0	-		-	-	Ξ	bearing -	Name and Address of the Owner o
105.W	H		97 94	27	Е	tenertone tenertone	Manager and the separate of Francisco productions of the party and the separate of the second of the
100 W	Ε		99	27	Ε	tenertone tenertone	Married with the second for the second
E	Е			Ε	Ε		Markey or with the second of the second
E	Е	E	Ξ	E	E		Mark you work regarded by the second con-
=	É	Ξ	Ξ	Ξ	Ξ		Markey with the service of the free beauty of the service of the s
	E						Married with the state of the first of the state of the s
10.0 10.0	п		W/ W/	-	÷	NAME AND ADDRESS OF THE PARTY NAME A	
10.3 10.3	=		W/ W/	-	Ξ	NAME AND ADDRESS OF THE PARTY O	Mark you with the same of the free base of the

	Date	Measured Liquid	Transducer Height	Base of Sump	Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Elevation	Leachate	measurement?		
LCS Number	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 2D	1/10/20	N/A	14.4	235.92	,	N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/17/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/24/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/21/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/28/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/6/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/13/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/20/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/27/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/3/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/16/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/23/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/30/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/21/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/28/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/4/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/11/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/18/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/25/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/2/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/9/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/16/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/23/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/21/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/28/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/4/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/11/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/18/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/25/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/1/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/8/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/15/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/22/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/29/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/5/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/12/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/25/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/3/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/18/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/24/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/7/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement


				Well Total Depth				
	Date	Measured Liquid	Transducer Depth	from Top of	Elevation of	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Casing (Ft.)	Leachate	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS-3D	1/10/20	49.0	N/A	140	,	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/17/20	46.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/24/20	41.6	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/31/20	41.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/7/20	43.6	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/14/20	47.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/21/20	48.6	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/28/20	48.9	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/6/20	49.9	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/13/20	47.3	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/20/20	62.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/27/20	50.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/3/20	45.9	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/10/20	49.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/16/20	52.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/23/20	51.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/1/20	55.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/7/20	50.0	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/14/20	54.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/21/20	40.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/28/20	50.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/4/20	50.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/11/20	54.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/19/20	52.5	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/26/20	52.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/2/20	60.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/9/20	60.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/17/20	61.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/23/20	60.5	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/31/20	60.6	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/7/20	59.0	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/14/20	51.2	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/21/20	59.0	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/28/20	48.2	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/4/20	52.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/11/20	50.3	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/18/20	58.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/25/20	59.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/1/20	59.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/8/20	48.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/15/20	57.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/22/20	57.3	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/5/20	62.5	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/12/20	59.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/19/20	58.6	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/25/20	57.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/3/20	58.2	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
								The pump in LCS-3D was non-operational on 12/10/20 after the liquid level
LCS-3D	12/10/20	59.2	N/A	140		Υ	Heron Dipper T	measurement. Pump repairs are scheduled to be completed on 12/14/20.
							• •	The pump in LCS-3D was non-operational on 12/10/20 after the liquid level
								measurement. Pump repairs were completed on 12/14/20. The pump was fully
LCS-3D	12/18/20	62.9	N/A	140		Υ	Heron Dipper T	operational for the rest of the reporting period.
LCS-3D	12/24/20	66.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/31/20	67.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
				-			11 -	The pump in LCS-3D was non-operational from 1/3/21 - 1/7/21. The pump was
	1/7/21	49.4	N/A	140		N	Heron Dipper T	repaired and became fully operational on 1/8/21.

## LCS-3D Liquid Level Below Ground Surface




	Date	Measured Liquid	Transducer Depth	Base of Sump	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Elevation	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 4B	1/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/17/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/24/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/31/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/14/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/21/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/28/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/6/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/13/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/20/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/27/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/3/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/16/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/23/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/30/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/14/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/21/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/28/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/4/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/11/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/18/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/26/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/2/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/9/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/16/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/23/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/31/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/14/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/21/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/28/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/4/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/11/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/18/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/25/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/1/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/8/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/15/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/22/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/29/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/5/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/12/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/19/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/25/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/3/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/18/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/24/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/31/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/7/21	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS

## LCS-4B Liquid Level Below Ground Surface



	Date	Measured Liquid	Transducer Height	Base of Sump		Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Elevation	Height of	Leachate	measurement?		
	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	Liquid (ft )	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 5B	1/10/20	12.4	21.9	235.3	34.3	269.60	Y	Dedicated Transducer	
LCS- 5B	1/17/20	11.3	21.9	235.3	33.2	268.50	Y	Dedicated Transducer	
LCS- 5B	1/24/20	13.0	21.9	235.3	34.9	270.20	Υ	Dedicated Transducer	
LCS- 5B	1/31/20	11.7	21.9	235.3	33.6	268.90	Y	Dedicated Transducer	
LCS- 5B	2/7/20	12.6	21.9	235.3	34.5	269.80	Y	Dedicated Transducer	
LCS- 5B	2/14/20	12.3	21.9	235.3	34.2	269.50	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	2/21/20 2/28/20	11.3 11.6	21.9 21.9	235.3 235.3	33.2 33.5	268.50 268.80	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	3/6/20	10.3	21.9	235.3	32.2	267.50	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B	3/13/20	11.2	21.9	235.3	33.1	268.40	Ϋ́	Dedicated Transducer  Dedicated Transducer	
LCS- 5B	3/20/20	12.3	21.9	235.3	34.2	269.50	Y	Dedicated Transducer	
LCS- 5B	3/27/20	12.2	21.9	235.3	34.1	269.40	Y	Dedicated Transducer	
LCS- 5B	4/3/20	11.9	21.9	235.3	33.8	269.10	Υ	Dedicated Transducer	
LCS- 5B	4/9/20	10.9	21.9	235.3	32.8	268.10	Υ	Dedicated Transducer	
LCS- 5B	4/16/20	11.3	21.9	235.3	33.2	268.50	Υ	Dedicated Transducer	
LCS- 5B	4/23/20	10.4	21.9	235.3	32.3	267.60	Y	Dedicated Transducer	
LCS- 5B	4/30/20	11.7	21.9	235.3	33.6	268.90	Y	Dedicated Transducer	
LCS- 5B	5/7/20	10.1	21.9	235.3	32.0	267.30	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	5/14/20 5/21/20	12.0 11.7	21.9 21.9	235.3 235.3	33.9 33.6	269.20 268.90	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	5/28/20	11.2	21.9	235.3	33.1	268.40	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B	6/4/20	11.1	21.9	235.3	33.0	268.30	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B	6/11/20	11.6	21.9	235.3	33.5	268.80	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B	6/18/20	9.3	21.9	235.3	31.2	266.50	Ϋ́	Dedicated Transducer	
LCS- 5B	6/25/20	11.4	21.9	235.3	33.3	268.60	Y	Dedicated Transducer	
LCS- 5B	7/2/20	8.9	21.9	235.3	30.8	266.10	Υ	Dedicated Transducer	
LCS- 5B	7/9/20	10.0	21.9	235.3	31.9	267.20	Y	Dedicated Transducer	
LCS- 5B	7/16/20	8.3	21.9	235.3	30.2	265.50	Υ	Dedicated Transducer	
LCS- 5B	7/23/20	12.4	21.9	235.3	34.3	269.60	Υ	Dedicated Transducer	
LCS- 5B	7/31/20	13.0	21.9	235.3	34.9	270.20	Y	Dedicated Transducer	
LCS- 5B	8/7/20	11.1	21.9	235.3	33.0	268.30	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	8/14/20 8/21/20	14.0 14.1	21.9 21.9	235.3 235.3	35.9 36.0	271.20 271.30	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	8/21/20	13.1	21.9	235.3	35.0	271.30	Y	Dedicated Transducer  Dedicated Transducer	
LCS- 5B	9/4/20	82.1	21.9	235.3	104.0	339.30	N	Dedicated Transducer	The LCS-5B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are anticipated to be completed the week of 9/7/20.
LCS- 5B	9/11/20	84.7	21.9	235.3	106.6	341.90	N	Dedicated Transducer	The LCS-5B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are anticipated to be completed the week of 9/7/20.
LCS- 5B	9/18/20	15.0	21.9	235.3	36.9	272.20	Y	Dedicated Transducer	The LCS-5B pump was replaced on 9/17/20 and was fully operational.
LCS- 5B	9/25/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer	The LCS-5B transducer was found to be non-operational on 9/21/20. The transducer was replaced on 9/24/20 and was fully operational.
LCS- 5B	10/1/20	13.9	21.9	235.3	35.8	271.10	Y	Dedicated Transducer	
LCS- 5B	10/8/20	14.0	21.9	235.3	35.9	271.20	Y	Dedicated Transducer	
	10/15/20 10/22/20	14.1	21.9	235.3 235.3	36.0 36.7	271.30 272.00	Y	Dedicated Transducer	
	10/22/20	14.8 14.2	21.9 21.9	235.3	36.7	272.00	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	11/5/20	14.1	21.9	235.3	36.0	271.40	Y	Dedicated Transducer  Dedicated Transducer	
	11/12/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer  Dedicated Transducer	
	11/19/20	14.2	21.9	235.3	36.1	271.40	Y	Dedicated Transducer	
	11/25/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer	
LCS- 5B	12/3/20	14.2	21.9	235.3	36.1	271.40	Y	Dedicated Transducer	
	12/10/20	14.0	21.9	235.3	35.9	271.20	Υ	Dedicated Transducer	
	12/18/20	13.9	21.9	235.3	35.8	271.10	Y	Dedicated Transducer	
	12/24/20	14.0	21.9	235.3	35.9	271.20	Υ	Dedicated Transducer	
	12/31/20	13.9	21.9	235.3	35.8	271.10	Υ	Dedicated Transducer	
LCS- 5B	1/7/21	13.9	21.9	235.3	35.8	271.10	Y	Dedicated Transducer	


## LCS-5B Liquid Level Above Quarry Floor



<sup>\*</sup>The LCS-5B pump was turned off on 8/31/20 for forecmain repairs leading to an increase in liquid level. The pump was replaced on 9/17/20.

	1		I =	n (0					
	Date Reading		Transducer Height above Floor of	Base of Sump Flevation	Height of	Elevation of Leachate	Pump on during measurement?		
LCS Number	Collected		Quarry (Ft.)	(Ft. MSL)	Liquid (ft )	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS-6B	1/10/20	9.2	9.4	429.52	18.6	448.12	(1/N) Y	Dedicated Transducer	Confinents
LCS- 0B	1/10/20	9.2	9.4	429.52	10.0	440.12	T	Dedicated Transducer	The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	1/17/20		9.4	429.52			N	Dedicated Transducer	pending replacement parts arrival.
200 05	1711720		0.1	120.02			.,	Dodioatoa Tranoados	The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	1/24/20		9.4	429.52			N	Dedicated Transducer	pending replacement parts arrival.
200 05	172 1720		0.1	120.02			.,	Dodioatoa Tranoados	The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	1/31/20		9.4	429.52			N	Dedicated Transducer	pending replacement parts arrival.
200 05	1701720		0.1	120.02			.,	Dodioatoa Tranoados	The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	2/7/20		9.4	429.52			N	Dedicated Transducer	pending replacement parts arrival.
									The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	2/14/20		9.4	429.52			N	Dedicated Transducer	pending replacement parts arrival.
									The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	2/21/20	N/A	N/A	429.52	27.8	457.32	N	Heron Dipper T	pending replacement parts arrival. Liquid level was measured manually.
									The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	2/28/20	N/A	N/A	429.52	28.3	457.82	N	Heron Dipper T	tentatively scheduled the week of 3/9/20. Liquid level was measured manually.
									The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is
LCS- 6B	3/6/20	N/A	N/A	429.52	28.0	457.52	N	Heron Dipper T	scheduled for 3/11/20. Liquid level was measured manually.
									The LCS-6B transducer was replaced on 3/11/20 and the pump became fully operational. The LCS-
									6B pump was observed to be non-operational on 3/12/20. The LCS-6B pump was replaced on
LCS- 6B	3/13/20	12.5	9.4	429.52	21.9	451.42	Υ	Dedicated Transducer	3/13/20. LCS-6B became fully operational on 3/13/20.
LCS- 6B	3/20/20	12.3	9.4	429.52	21.7	451.22	Y	Dedicated Transducer	
LCS- 6B	3/27/20	11.9	9.4	429.52	21.3	450.82	Υ	Dedicated Transducer	
LCS- 6B	4/3/20	11.5	9.4	429.52	20.9	450.42	Υ	Dedicated Transducer	
LCS- 6B	4/10/20	12.0	9.4	429.52	21.4	450.92	Υ	Dedicated Transducer	
LCS- 6B	4/16/20	12.4	9.4	429.52	21.8	451.32	Y	Dedicated Transducer	
									The LCS-6B VFD was observed to be non-operational on 4/23/20. The VFD was replaced on
									4/23/20 and LCS-6B became fully operational. A level sensor reading was not collected during the
LCS- 6B	4/23/20		9.4	429.52			Υ	Dedicated Transducer	weekly reporting period due to VFD communication loss with the site's SCADA system.
LCS- 6B	4/30/20	8.9	9.4	429.52	18.3	447.82	Υ	Dedicated Transducer	
LCS- 6B	5/7/20	9.0	9.4	429.52	18.4	447.92	Y	Dedicated Transducer	
LCS- 6B	5/14/20	13.3	9.4	429.52	22.7	452.22	Y	Dedicated Transducer	
LCS- 6B	5/21/20	13.3	9.4	429.52	22.7	452.22	Υ	Dedicated Transducer	
LCS- 6B	5/28/20	7.8	9.4	429.52	17.2	446.72	Y	Dedicated Transducer	
LCS- 6B	6/4/20	8.9	9.4	429.52	18.3	447.82	Y	Dedicated Transducer	
LCS- 6B	6/11/20	7.9	9.4	429.52	17.3	446.82	Υ	Dedicated Transducer	
LCS- 6B	6/18/20	8.9	9.4	429.52	18.3	447.82	Υ	Dedicated Transducer	
LCS- 6B	6/25/20	8.7	9.4	429.52	18.1	447.62	Υ	Dedicated Transducer	
LCS- 6B	7/2/20	9.2	9.4	429.52	18.6	448.12	Υ	Dedicated Transducer	
LCS- 6B	7/9/20	9.0	9.4	429.52	18.4	447.92	Υ	Dedicated Transducer	
LCS- 6B	7/16/20	8.7	9.4	429.52	18.1	447.62	Υ	Dedicated Transducer	
LCS- 6B	7/23/20	8.6	9.4	429.52	18.0	447.52	Υ	Dedicated Transducer	
LCS- 6B	7/31/20	8.6	9.4	429.52	18.0	447.52	Υ	Dedicated Transducer	
LCS- 6B	8/7/20	8.4	9.4	429.52	17.8	447.32	Υ	Dedicated Transducer	
LCS- 6B	8/14/20	8.7	9.4	429.52	18.1	447.62	Y	Dedicated Transducer	
LCS- 6B	8/21/20	7.2	9.4	429.52	16.6	446.12	Υ	Dedicated Transducer	
LCS- 6B	8/28/20	8.5	9.4	429.52	17.9	447.42	Y	Dedicated Transducer	
									The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are
LCS- 6B	9/4/20	15.5	9.4	429.52	24.9	454.42	N	Dedicated Transducer	anticipated to be completed the week of 9/7/20.
									The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are
LCS- 6B	9/11/20	19.4	9.4	429.52	28.8	458.32	N	Dedicated Transducer	anticipated to be completed the week of 9/7/20.
									The LOC OR
1									The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs were
100.00	0/40/00	00.4		100 50	00.5	450.00		Dedicated Toront	completed on 9/9/20. The pump in LCS-6B was non-operational when attempts were made to turn it
LCS- 6B	9/18/20	20.1	9.4	429.52	29.5	459.02	N	Dedicated Transducer	back on after forcemain repairs. Pump repairs are tentatively scheduled for the week of 9/21/20.
									The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs were
									completed on 9/9/20. The pump in LCS-6B was non-operational when attempts were made to turn it
LCS- 6B	9/25/20	N/A	N/A	429.52	24.1	453.62	N	Heron Dipper T	back on after forcemain repairs. The electric pump in LCS-6B will be converted to a pneumatic pump the week of 9/28/20. Liquid level was measured manually.
FC9- 0B	9/25/20	N/A	N/A	429.52	24.1	453.62	N	Heron Dipper I	The electric pump in LCS-6B was converted to a pneumatic pump on 9/30/20. Liquid level was
LCS- 6B	10/1/20	N/A	N/A	429.52	14.3	443.82	Y	Heren Dinner T	The electric pump in LCS-6B was converted to a pneumatic pump on 9/30/20. Liquid level was measured manually.
LCS- 6B	10/1/20	N/A N/A	N/A N/A	429.52 429.52	6.9	436.42	Y	Heron Dipper T Heron Dipper T	measured manually.
LCS- 6B	10/8/20	N/A N/A	N/A N/A	429.52 429.52	7.1	436.42	Y	Heron Dipper T	
		N/A N/A	N/A N/A	429.52	7.1	436.62	Υ Υ		
LCS- 6B	10/22/20 10/29/20	N/A N/A	N/A N/A	429.52 429.52	7.5 8.0	437.02	Y	Heron Dipper T	
LCS- 6B LCS- 6B	10/29/20	N/A N/A	N/A N/A	429.52 429.52	5.3	437.52	Y	Heron Dipper T Heron Dipper T	
LCS- 6B	11/5/20	N/A N/A	N/A N/A	429.52	5.8	434.82	Y	Heron Dipper T	
LCS- 6B	11/12/20	N/A N/A	N/A N/A	429.52 429.52	5.8	435.32 434.82	Y		
LCS- 6B	11/19/20	N/A N/A	N/A N/A	429.52 429.52	5.3	434.82	Y	Heron Dipper T	
				429.52 429.52	5.3		Y	Heron Dipper T	
LCS- 6B	12/3/20	N/A	N/A			434.52		Heron Dipper T	
LCS- 6B	12/10/20	N/A N/A	N/A N/A	429.52	5.8	435.32	Y	Heron Dipper T	
LCS- 6B LCS- 6B	12/18/20 12/24/20	N/A N/A	N/A N/A	429.52 429.52	5.2 5.1	434.72 434.62	Y	Heron Dipper T Heron Dipper T	
LCS- 6B		N/A N/A	N/A N/A	429.52 429.52	5.1	434.62 434.92	Y		Pump operational; liquid level measured manually
LCS- 6B LCS- 6B	12/31/20	N/A N/A		429.52 429.52	5.4	434.92 435.02	Y	Heron Dipper T	
FC9- 0B	1/7/21	n/A	N/A	429.52	ნ.ნ	433.02	ř	Heron Dipper T	Pump operational; liquid level measured manually

## LCS-6B Liquid Level Above Quarry Floor



The transducer became non-operational on 1/13/20. Liquid level was measured manually on 2/21/20, 2/28/20 and 3/6/20. The transducer became operational on 3/13/20. The VFD was observed to be non-operational on 4/23/20, it was replaced on 4/23/20, however the level sensor reading was not taken due to VFD communication loss with SCADA. The LCS-6B pump was turned off on 8/31/20 for forcemain repairs leading to an increase in liquid level. The electric pump was converted to a pneumatic pump on 9/30/20.