
	na hada	Stemant roof	Transfers Topic See Topic Trains	Base Placing Broaders	Transmit .		
10.7				Н	ŀ	****	
-	=				4		
					Ė		
	III			ш	44	****	
					-		
	Ш	H	H	H	ť		
		Н	Н		H	-	
	Ш	Ш	H	ı	Ш		Committee of the second section of the
	Н	H	ii	н	4		
-	=				4		
	Ш				Ш		
-	=				Н		
	Ш	I		Ш	Ш		
MA.W	wer	_	91	ALC:		Select Tendor	Payabla ta Bellianiana, Nautomatia Namber, Payababbar
	Ш	I	H	H	H		
-	≡				Н		
-	II		H	H	Ψ		
					Н		
	i	I	ł	ı	ł		
100.00	_		90	-		NAME AND ADDRESS OF THE OWNER, TH	Top the national full artists a state of the specific
	_		-	-	-		Top Pin servers top antender operations, or as Top Pin servers top antender operations, or as
-	_	I		l	l		Any Promisers high probability special should are hop Promisers high probability special should be
					Н		Any Pin remain frequents have represent them to the
				Н	Н		And the resemble that the special property con-
175.W	March March		977	200	٠,	NAME TO AN	Name and Address of the Association
103.75	100		10	ě	ľ	Separation and Separa	And the second field of make appearance in
100.00			90	-		NAME AND ADDRESS OF THE OWNER, TH	Any Ph. Services Full and Strakes operant project to
-		I		l	l		They are not to the common operation to the common operation to the common operation of the common operation ope
15.7	-		11	- max	Ξ	boscone	
-		Ē	-		F		
	E						
20.0			-		E	table from	NUMBER OF STREET
MAY.	100	=	901	AN AN	-	Separation	They represent designs to an artist to the assessment of the property of the second of
10.0	-		-	-	Ξ	NAME TO AN	Appendix Appendix and Appendix and a second
=	F		=				And the state of t
_	F						
	E						Married water representative frequency or principles
							Married week superiority between pro-
100.00		_	90	-		NAME AND ADDRESS OF	Mark you within to you about Property and
105.30		I	90		1	NAME AND ADDRESS OF THE PARTY O	Mark you with the second of the second
					Н		Mark you will be supplied by the property of the same
				Н	Н		Annual Control of the
	_			Н	ŀ		Married Married Street, Street
							Mark you would be seen and the forest party and the second
100.00	-		-		1	NAME AND ADDRESS OF	Mark you would be seen and the forest partition of the
US.W	100		97	82	1	Separation of the Separation o	Mark you would never named for the street ground
US.W	100		97	82	1	Separation of the Contract of	Mark you would never named for the street ground
	_		-	-	-		Mark you will be to be a first or the second
-		I		l	l		Mark you window to pay a 1973 from the common of the commo
_	=			Н	Н		Mark you works seem of the frequency of the
	=				Н		Markey was the same of the franchist and
175.76	-		97	×	1	NAME OF TAXABLE PARTY.	NAME AND ADDRESS OF THE OWNER, WHEN PERSON ADDRESS OF THE OWNER, WHEN PERSON AND ADDRESS OF THE OWNER, WHEN
175.70	-		90	N.	1	NAME AND ADDRESS OF THE PARTY NAME A	Mark you work when the Park County of the
100.0					Н	Section Section	Mark you will be reported by the property of the same
				Н	ľ		Mark part and an extension of the party of the same
				Н	ľ		Mark you window suggest a 1975 From September 1970 A
				Н	ľ		Mark you window service and the August operations of the Mark your window service and the August operations of the Augus
100.0	-		101	-		Temper Temper	Was his many release to a principle of the second
MAR.	100		90	AN AN		Telephone Telephone	Marie party maries conservatives frequency and an activative frequency and an activative frequency and activative frequen
105.30		I	90		1	NAME AND ADDRESS OF THE PARTY O	Mark you with the second of the second
_	_			Н	Н		Mark you would never not the frequency of the
	=				Н		Married water supplied the forest property and
-	-	I		l	l		Mark you window separate of the following or great
_	=			Н	Н		Mark you within some order for party or and
USW			W	mv.	,	NAME AND ADDRESS OF	Mark you wide to be a live of the property of the last
103.70	-		97	1	í	Separation and the separation of the separation	Mark you will be reported by the property of the same
100.00	-		8	ı	ľ	NAME AND ADDRESS OF	Mark you with the sales of the first special party of the sales of the
	_		-	-	-		And you was a super and a super a
			-	-	-		Name and Address of the Owner, where
	Е		=	=	Ξ		Mark you window service of the Property of Street,
=	F		=				
10.0	-		97	22	-	Separation of the Contract of	
10.0	=		W/	-	÷	Total Total	Maria para mandra di Araba da
10.0	E		-	_	Ë	NAME AND ADDRESS OF	Mary page and the supplement of the supplement o
E	E				E		Married State Super State Property and State Sta
	E						Married with higher 1972 for the property
╚	E				Ë		Mark you within topics of the frequency of the
20.0	E	E		_	ΕĒ	TATAL TRANS	Mark you wishes super a first frequency of the
100.00 100.00	=	E	90	27	Ε	NAME AND ADDRESS OF THE PARTY NAME A	Mark yet Marks annea all' I franchise de la colonia. Mark yet marks annea all' I franchise de la colonia.
10.0	E		-	-	Ξ	NAME TO AN	Mark you with the same of the
=	F		=	=	=		
=	F		=	=	=		
=	F		=				
=	F					_	Mark you work to you need to be a proper of the
10.0	Ξ		W	20	-	TATAL TOTAL	Mary page and the second of th
10.0			10	-	=	NAME AND ADDRESS OF	Mary page and the supplement of the supplement o
10.0	E		-	_		NAME AND ADDRESS OF	Mark you with many of the forest party of
E	E				E		Married State Super State Property and State Sta
E	E	E	Ξ	E	E		Mark you work to pay the Property of the State of the Sta
E	Е	E	Ξ	E	E		Mark you would be part of the first own products of the contract of the contra
_	E		-	-	F		Mark you with the same of the frequency of the same of the frequency of the same of the sa
10.0	=		97	=	÷	Mariotal Mariotal	Mary pay and the same of the following property of the same of the
10.0	Ξ		W/	-	÷	NAME AND ADDRESS OF THE PARTY NAME A	Marie para materia de para a forma de la constitución de la constituci
	=				=		Maria de Caración
	=				=		Maryon was a special for the contract of
	E						Mark you within to pay of the frequency of the
E	Ē	E	ᄐ	E	E		Mark you window began offered from the party of growth
100.00	100		W.	- max	÷	THE PERSON	Mark you with the same of the frequency of the
10.0	-		-	-	÷	teractories.	Mark you wish super about for the party of the same
10.0	-		- 20	-	Ė	teractories.	Mark you wish super about for the party of the same
=	F					_	Mary or wide with the second free party of the second seco
=	F			=	=		The second specific to the second
	E						Married water separative frequency and
	=				=		Married water topic of the following of the
10.0	=		W	200	÷	TATAL TOTAL	Mark you with many of the foreign and
10.0	Ξ		97 97	200		TATAL TATAL	Mark you with the same of the forest party and
E	Е	E	Ξ	E	E		Mark you with annual of the forest party and the same of the same
	_						Mark you work to be a series of the series o



	Date	Measured Liquid	Transducer Height	Base of Sump	Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Elevation	Leachate	measurement?		
LCS Number	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 2D	3/20/20	N/A	14.4	235.92	,	N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/27/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/3/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/16/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/23/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/30/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/21/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/28/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/4/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/11/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/18/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/25/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/2/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/9/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/16/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/23/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/21/20 8/28/20	N/A N/A	14.4 14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/4/20	N/A N/A	14.4	235.92 235.92		N N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D LCS- 2D	9/11/20	N/A N/A	14.4	235.92		N N	Dedicated Transducer Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/11/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/25/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/1/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/8/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/15/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/22/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/29/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/5/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/12/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/25/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/3/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/18/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/24/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/7/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/14/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/21/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/28/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/4/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/11/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/18/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/25/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/4/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/11/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/18/21	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement


	Date	Measured Liquid	Transducer Depth	Well Total Depth from Top of	Elevation of	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Casing (Ft.)	Leachate	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS-3D	3/20/20	62.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/27/20	50.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/3/20 4/10/20	45.9 49.7	N/A N/A	140 140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D LCS-3D	4/10/20	49.7 52.2	N/A N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually Pump operational; liquid level measured manually
LCS-3D LCS-3D	4/16/20	52.2 51.8	N/A N/A	140		Y	Heron Dipper T Heron Dipper T	Pump operational; liquid level measured manually Pump operational; liquid level measured manually
LCS-3D	5/1/20	55.6	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/7/20	50.0	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/14/20	54.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/21/20	40.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/28/20	50.7	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/4/20	50.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/11/20	54.8	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/19/20	52.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/26/20	52.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/2/20	60.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually Pump operational; liquid level measured manually
LCS-3D LCS-3D	7/9/20 7/17/20	60.4 61.1	N/A N/A	140 140		Y	Heron Dipper T Heron Dipper T	Pump operational; liquid level measured manually Pump operational; liquid level measured manually
LCS-3D	7/17/20	60.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/31/20	60.6	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/7/20	59.0	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/14/20	51.2	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/21/20	59.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/28/20	48.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/4/20	52.1	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/11/20	50.3	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/18/20	58.0	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/25/20	59.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/1/20 10/8/20	59.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D LCS-3D	10/8/20	48.8 57.9	N/A N/A	140 140		Y	Heron Dipper T Heron Dipper T	Pump operational; liquid level measured manually Pump operational; liquid level measured manually
LCS-3D	10/13/20	57.3	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/5/20	62.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/12/20	59.8	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/19/20	58.6	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/25/20	57.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/3/20	58.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
								The pump in LCS-3D was non-operational on 12/10/20 after the liquid level
LCS-3D	12/10/20	59.2	N/A	140		Y	Heron Dipper T	measurement. Pump repairs are scheduled to be completed on 12/14/20.
								The pump in LCS-3D was non-operational on 12/10/20 after the liquid level
	40/40/00	20.0		440		Y	5: -	measurement. Pump repairs were completed on 12/14/20. The pump was fully
LCS-3D LCS-3D	12/18/20 12/24/20	62.9 66.0	N/A N/A	140 140		Y	Heron Dipper T Heron Dipper T	operational for the rest of the reporting period. Pump operational; liquid level measured manually
LCS-3D	12/31/20	67.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
L00-0D	12/01/20	01.1	19/73	1-10		'	Horon Dipper 1	The pump in LCS-3D was non-operational from 1/3/21 - 1/7/21. The pump was
LCS-3D	1/7/21	49.4	N/A	140		N	Heron Dipper T	repaired and became fully operational on 1/8/21.
								The pump in LCS-3D was non-operational from 1/11/21 - 1/13/21. The pump was
LCS-3D	1/14/21	54.8	N/A	140		Y	Heron Dipper T	repaired and became fully operational on 1/14/21.
LCS-3D	1/21/21	58.4	N/A	140		Υ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/28/21	55.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/4/21	60.1	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
								Liquid level measured manually. The LCS-3D pump was non-operational on 2/12/21
100.00	0/44/04	F0.0	N1/A	440		,,	Harris B' T	due to a frozen forcemain. The forcemain was frozen the remainder of the weekly
LCS-3D	2/11/21	58.6	N/A	140		Y	Heron Dipper T	reporting period.
								Liquid level measured manually. The LCS-3D pump was non-operational since
LCS-3D	2/18/21	43.2	N/A	140		N	Heron Dipper T	2/12/21 due to a frozen forcemain. The forcemain was frozen the entirety of the weekly reporting period.
LU3-3D	Z/ 10/Z I	43.2	IN/A	140		IN	Herori Dipper 1	weekly reporting period.
								Liquid level measured manually. The LCS-3D pump was non-operational on 2/12/21
LCS-3D	2/25/21	56.3	N/A	140		Y	Heron Dipper T	due to a frozen forcemain. The pump became operational again on 2/23/21.
LCS-3D	3/4/21	61.7	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/11/21	62.1	N/A	140		Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
ししつ-3D								

LCS-3D Liquid Level Below Ground Surface




	Date	Measured Liquid	Transducer Depth	Base of Sump	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Elevation	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 4B	3/20/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/27/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/3/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/16/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/23/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/30/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/14/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/21/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/28/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/4/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/11/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/18/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/26/20	74.0	81.0	244.00	Υ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/2/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/9/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/16/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/23/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/31/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/14/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/21/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/28/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/4/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/11/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/18/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/25/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/1/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/8/20	74.0 74.0	81.0 81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	10/15/20 10/22/20	74.0	81.0	244.00 244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/22/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/5/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B		74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	11/12/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/19/20 11/25/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/3/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
					Y Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	12/10/20 12/18/20	74.0 74.0	81.0 81.0	244.00 244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	12/18/20	74.0	81.0 81.0	244.00	Y		
LCS- 4B LCS- 4B	12/24/20	74.0	81.0 81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/7/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/1/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/14/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	1/21/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/4/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/4/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	2/11/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/18/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B LCS- 4B	3/4/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/11/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/11/21	74.0	81.0	244.00	Y	Dedicated Transducer Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS Pump operational, no flow detected, liquid level >74.0' BGS
LU3- 4D	3/10/21	14.0	01.0	Z44.UU	T	Dedicated Hallsducer	r ump operational, no now detected, liquid level >74.0 BGS

LCS-4B Liquid Level Below Ground Surface



	Date	Measured Liquid	Transducer Height	Page of Sump		Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Base of Sump Elevation	Height of	Leachate	measurement?		
LCS Number	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	Liquid (ft)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 5B	3/20/20	12.3	21.9	235.3	34.2	269.50	Υ Υ	Dedicated Transducer	Comments
LCS- 5B	3/27/20	12.2	21.9	235.3	34.1	269.40	Υ	Dedicated Transducer	
LCS- 5B	4/3/20	11.9	21.9	235.3	33.8	269.10	Y	Dedicated Transducer	
LCS- 5B	4/9/20	10.9	21.9	235.3	32.8	268.10	Υ	Dedicated Transducer	
LCS- 5B	4/16/20	11.3	21.9	235.3	33.2	268.50	Υ	Dedicated Transducer	
LCS- 5B	4/23/20	10.4	21.9	235.3	32.3	267.60	Y	Dedicated Transducer	
LCS- 5B	4/30/20	11.7	21.9	235.3	33.6	268.90	Y	Dedicated Transducer	
LCS- 5B	5/7/20	10.1	21.9	235.3	32.0	267.30	Y	Dedicated Transducer	
LCS- 5B	5/14/20	12.0	21.9	235.3	33.9	269.20	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	5/21/20 5/28/20	11.7 11.2	21.9 21.9	235.3 235.3	33.6 33.1	268.90 268.40	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	6/4/20	11.1	21.9	235.3	33.0	268.30	Y	Dedicated Transducer	
LCS- 5B	6/11/20	11.6	21.9	235.3	33.5	268.80	Ϋ́	Dedicated Transducer	
LCS- 5B	6/18/20	9.3	21.9	235.3	31.2	266.50	Ϋ́	Dedicated Transducer	
LCS- 5B	6/25/20	11.4	21.9	235.3	33.3	268.60	Υ	Dedicated Transducer	
LCS- 5B	7/2/20	8.9	21.9	235.3	30.8	266.10	Υ	Dedicated Transducer	
LCS- 5B	7/9/20	10.0	21.9	235.3	31.9	267.20	Y	Dedicated Transducer	
LCS- 5B	7/16/20	8.3	21.9	235.3	30.2	265.50	Υ	Dedicated Transducer	
LCS- 5B	7/23/20	12.4	21.9	235.3	34.3	269.60	Y	Dedicated Transducer	
LCS- 5B	7/31/20	13.0	21.9	235.3	34.9	270.20	Υ	Dedicated Transducer	
LCS- 5B	8/7/20	11.1	21.9	235.3	33.0	268.30	Y	Dedicated Transducer	
LCS- 5B	8/14/20	14.0 14.1	21.9	235.3 235.3	35.9	271.20 271.30	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	8/21/20 8/28/20	13.1	21.9 21.9	235.3	36.0 35.0	271.30	Y	Dedicated Transducer Dedicated Transducer	
LC3- 3B	0/20/20	13.1	21.9	235.3	35.0	270.30	T	Dedicated Transducer	The LCS-5B pump was turned off on 8/31/20 for forcemain
									repairs. Forcemain repairs are anticipated to be completed the
LCS- 5B	9/4/20	82.1	21.9	235.3	104.0	339.30	N	Dedicated Transducer	week of 9/7/20.
200 02	0/ 1/20	02.1	21.0	200.0	101.0	000.00	.,	Boaloutou Tranoutou	The LCS-5B pump was turned off on 8/31/20 for forcemain
									repairs. Forcemain repairs are anticipated to be completed the
LCS- 5B	9/11/20	84.7	21.9	235.3	106.6	341.90	N	Dedicated Transducer	week of 9/7/20.
									The LCS-5B pump was replaced on 9/17/20 and was fully
LCS- 5B	9/18/20	15.0	21.9	235.3	36.9	272.20	Υ	Dedicated Transducer	operational.
									The LCS-5B transducer was found to be non-operational on
									9/21/20. The transducer was replaced on 9/24/20 and was fully
LCS- 5B	9/25/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer	operational.
LCS- 5B LCS- 5B	10/1/20 10/8/20	13.9 14.0	21.9 21.9	235.3 235.3	35.8 35.9	271.10 271.20	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	10/6/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer	
LCS- 5B	10/13/20	14.8	21.9	235.3	36.7	272.00	Y	Dedicated Transducer	
LCS- 5B	10/29/20	14.2	21.9	235.3	36.1	271.40	Ϋ́	Dedicated Transducer	
LCS- 5B	11/5/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer	
LCS- 5B	11/12/20	14.1	21.9	235.3	36.0	271.30	Y	Dedicated Transducer	
LCS- 5B	11/19/20	14.2	21.9	235.3	36.1	271.40	Υ	Dedicated Transducer	
LCS- 5B	11/25/20	14.1	21.9	235.3	36.0	271.30	Υ	Dedicated Transducer	
LCS- 5B	12/3/20	14.2	21.9	235.3	36.1	271.40	Υ	Dedicated Transducer	
LCS- 5B	12/10/20	14.0	21.9	235.3	35.9	271.20	Υ	Dedicated Transducer	
LCS- 5B	12/18/20	13.9	21.9	235.3	35.8	271.10	Y	Dedicated Transducer	
LCS- 5B	12/24/20	14.0	21.9	235.3	35.9	271.20	Y	Dedicated Transducer	
LCS- 5B	12/31/20	13.9	21.9	235.3	35.8	271.10	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	1/7/21 1/14/21	13.9 13.8	21.9 21.9	235.3 235.3	35.8 35.7	271.10 271.00	Y	Dedicated Transducer	
LCS- 5B LCS- 5B	1/14/21	13.8	21.9	235.3	35.7 35.7	271.00	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	1/21/21	13.8	21.9	235.3	35.7	271.00	Y	Dedicated Transducer Dedicated Transducer	
LCS- 5B	2/4/21	13.9	21.9	235.3	35.8	271.10	Y	Dedicated Transducer	
LCS- 5B	2/11/21	13.6	21.9	235.3	35.5	270.80	Ϋ́	Dedicated Transducer	
LCS- 5B	2/18/21	48.2	21.9	235.3	70.1	305.40	N	Dedicated Transducer	The pump in LCS-5B was non-operational on 2/15/21 due to a frozen forcemain. The forcemain was frozen the entirety of the weekly reporting period.
LCS- 5B	2/25/21	13.6	21.9	235.3	35.5	270.80	Y	Dedicated Transducer	The pump in LCS-5B was non-operational on 2/15/21 due to a frozen forcemain. The pump became operational again on 2/25/21.
							Y	Dedicated Transducer	
LCS- 5B	3/4/21	13.8	21.9	235.3	35.7	271.00	T	Dedicated Hallsducel	
	3/4/21 3/11/21	13.8	21.9	235.3 235.3	35.7	271.00	Y	Dedicated Transducer Dedicated Transducer	


LCS-5B Liquid Level Above Quarry Floor



^{*}The LCS-5B pump was turned off on 8/31/20 for forecmain repairs leading to an increase in liquid level. The pump was replaced on 9/17/20.

	1 - 1		I =						T
	Date		Transducer Height above Floor of	Base of Sump	11-1-64 -6	Elevation of	Pump on during		
LCS Number	Reading Collected	V		Elevation (Ft. MSL)	Height of Liquid (ft)	Leachate (Ft. MSL)	measurement?	Liquid level meter used	Comments
LCS Number	3/20/20	12.3	Quarry (Ft.) 9.4	429.52	21.7	451.22	(Y/N) Y	Dedicated Transducer	Comments
LCS- 6B	3/20/20	11.9	9.4	429.52 429.52	21.7	451.22	Y	Dedicated Transducer Dedicated Transducer	
LCS- 6B	4/3/20	11.5	9.4	429.52 429.52	20.9	450.62	Y	Dedicated Transducer Dedicated Transducer	
LCS- 6B	4/10/20	12.0	9.4	429.52	21.4	450.92	Y	Dedicated Transducer	
LCS- 6B	4/16/20	12.4	9.4	429.52	21.8	451.32	Y	Dedicated Transducer	
LC3- 0B	4/10/20	12.4	9.4	429.52	21.0	401.32	-	Dedicated Transducer	
									The LCS-6B VFD was observed to be non-operational on 4/23/20. The VFD was replaced on 4/23/20 and LCS-6B became fully operational. A level sensor reading was not collected during the
LCS- 6B	4/23/20		9.4	429.52	10.0		Y	Dedicated Transducer	weekly reporting period due to VFD communication loss with the site's SCADA system.
LCS- 6B	4/30/20	8.9	9.4	429.52	18.3	447.82	Y	Dedicated Transducer	
LCS- 6B	5/7/20	9.0	9.4	429.52	18.4	447.92	Y	Dedicated Transducer	
LCS- 6B	5/14/20	13.3	9.4	429.52	22.7	452.22	Y	Dedicated Transducer	
LCS- 6B LCS- 6B	5/21/20 5/28/20	13.3 7.8	9.4 9.4	429.52 429.52	22.7 17.2	452.22 446.72	Y	Dedicated Transducer Dedicated Transducer	
		8.9	9.4				Y		
LCS- 6B LCS- 6B	6/4/20 6/11/20	7.9	9.4	429.52 429.52	18.3 17.3	447.82 446.82	Y	Dedicated Transducer Dedicated Transducer	
LCS- 6B	6/11/20	7.9 8.9	9.4	429.52 429.52	17.3	446.82	Y	Dedicated Transducer Dedicated Transducer	
	6/18/20	8.9 8.7	9.4	429.52 429.52		447.62	Y	Dedicated Transducer Dedicated Transducer	
LCS- 6B		9.2	9.4	429.52 429.52	18.1	447.62	Y		
LCS- 6B	7/2/20				18.6	448.12 447.92	Y	Dedicated Transducer	
LCS- 6B	7/9/20	9.0 8.7	9.4	429.52	18.4	447.92 447.62	Y	Dedicated Transducer	
LCS- 6B	7/16/20		9.4 9.4	429.52 429.52	18.1 18.0	447.62 447.52	Y	Dedicated Transducer	
LCS- 6B	7/23/20	8.6					Y	Dedicated Transducer	
LCS- 6B	7/31/20	8.6	9.4	429.52	18.0	447.52	Y	Dedicated Transducer	
LCS- 6B	8/7/20 8/14/20	8.4 8.7	9.4 9.4	429.52 429.52	17.8	447.32 447.62	Y	Dedicated Transducer	
LCS- 6B		7.2	9.4	429.52 429.52	18.1 16.6	446.12	Y Y	Dedicated Transducer	
LCS- 6B	8/21/20		9.4				Y	Dedicated Transducer	
LCS- 6B	8/28/20	8.5	9.4	429.52	17.9	447.42	Y	Dedicated Transducer	The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are
LCS- 6B	9/4/20	15.5	9.4	429.52	24.9	454.42	N	Dedicated Transducer	The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are anticipated to be completed the week of 9/7/20. The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs are
LCS- 6B	9/11/20	19.4	9.4	429.52	28.8	458.32	N	Dedicated Transducer	anticipated to be completed the week of 9/7/20.
LCS- 6B	9/18/20	20.1	9.4	429.52	29.5	459.02	N	Dedicated Transducer	The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs were completed on 9/9/20. The pump in LCS-6B was non-operational when attempts were made to turn back on after forcemain repairs. Pump repairs are tentatively scheduled for the week of 9/21/20. The LCS-6B pump was turned off on 8/31/20 for forcemain repairs. Forcemain repairs were
LCS- 6B	9/25/20	N/A	N/A	429.52	24.1	453.62	N	Heron Dipper T	completed on 9/9/20. The pump in LCS-6B was non-operational when attempts were made to turn back on after forcemain repairs. The electric pump in LCS-6B will be converted to a pneumatic pump the week of 9/28/20. Liquid level was measured manually. The electric pump in LCS-6B was converted to a pneumatic pump on 9/30/20. Liquid level was
LCS- 6B	10/1/20	N/A	N/A	429.52	14.3	443.82	Y	Heron Dipper T	measured manually.
LCS- 6B	10/8/20	N/A	N/A	429.52	6.9	436.42	Y	Heron Dipper T	,
LCS- 6B	10/15/20	N/A	N/A	429.52	7.1	436.62	Ϋ́	Heron Dipper T	
LCS- 6B	10/22/20	N/A	N/A	429.52	7.5	437.02	Ϋ́	Heron Dipper T	
LCS- 6B	10/29/20	N/A	N/A	429.52	8.0	437.52	Υ	Heron Dipper T	
LCS- 6B	11/5/20	N/A	N/A	429.52	5.3	434.82	Υ	Heron Dipper T	
LCS- 6B	11/12/20	N/A	N/A	429.52	5.8	435.32	Y	Heron Dipper T	
LCS- 6B	11/19/20	N/A	N/A	429.52	5.3	434.82	Υ	Heron Dipper T	
LCS- 6B	11/25/20	N/A	N/A	429.52	5.3	434.82	Υ	Heron Dipper T	
LCS- 6B	12/3/20	N/A	N/A	429.52	5.0	434.52	Y	Heron Dipper T	
LCS- 6B	12/10/20	N/A	N/A	429.52	5.8	435.32	Υ	Heron Dipper T	
LCS- 6B	12/18/20	N/A	N/A	429.52	5.2	434.72	Υ	Heron Dipper T	
LCS- 6B	12/24/20	N/A	N/A	429.52	5.1	434.62	Υ	Heron Dipper T	
LCS- 6B	12/31/20	N/A	N/A	429.52	5.4	434.92	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS- 6B	1/7/21	N/A	N/A	429.52	5.5	435.02	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS- 6B	1/14/21	N/A	N/A	429.52	7.5	437.02	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS- 6B	1/21/21	N/A	N/A	429.52	6.7	436.22	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS- 6B	1/28/21	N/A	N/A	429.52	6.7	436.22	Ϋ́	Heron Dipper T	Pump operational; liquid level measured manually
LCS- 6B	2/4/21	N/A	N/A	429.52	6.8	436.32	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS- 6B	2/11/21	N/A	N/A	429.52	14.6	444.12	N N	Heron Dipper T	The LCS-6B pump was non-operational on 2/9/21 due to a frozen forcemain. The forcemain was frozen the remainder of the weekly reporting period.
LCS- 6B	2/18/21	N/A	N/A	429.52	16.5	446.02	N	Heron Dipper T	The LCS-6B pump was non-operational since 2/9/21 due to a frozen forcemain. The forcemain was frozen the entirety of the weekly reporting period.
		N/A		400.50		407.50	,		The LCS-6B pump was non-operational on 2/9/21 due to a frozen forcemain. The pump became
100.05	0.00 = 10.4		N/A	429.52	8.0	437.52	Υ	Heron Dipper T	operational again on 2/22/21
LCS- 6B	2/25/21				7 -	40= 00			
LCS- 6B	3/4/21	N/A	N/A	429.52	7.7	437.22	Y	Heron Dipper T	Pump operational; liquid level measured manually
					7.7 7.1 6.9	437.22 436.62 436.42	Y	Heron Dipper T Heron Dipper T Heron Dipper T	Pump operational; liquid level measured manually Pump operational; liquid level measured manually Pump operational; liquid level measured manually

LCS-6B Liquid Level Above Quarry Floor



The VFD was observed to be non-operational on 4/23/20, it was replaced on 4/23/20, however the level sensor reading was not taken due to VFD communication loss with SCADA. The LCS-6B pump was turned off on 8/31/20 for forcemain repairs leading to an increase in liquid level. The electric pump was converted to a pneumatic pump on 9/30/20.