

LCS-6B Liquid Level Above Quarry Floor




The transducer became non-operational on 1/13/20. Liquid level was measured manually on 2/21/20, 2/28/20 and 3/6/20. The transducer became operational on 3/13/20. The VFD was observed to be non-operational on 4/23/20, it was replaced on 4/23/20, however the level sensor reading was not taken due to VFD communication loss with SCADA.




	Date	Measured Liquid	Transducer Height	Base of Sump	Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Elevation	Leachate	measurement?		
LCS Number	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 2D	5/24/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/31/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/7/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/14/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/21/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	6/28/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/5/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/12/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/18/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	7/25/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/2/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/9/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/16/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/23/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	8/30/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/6/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/13/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/20/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	9/27/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/4/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/11/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/18/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	10/25/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/1/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/8/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/15/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	11/29/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/6/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/13/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/20/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	12/27/19	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/3/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/17/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/24/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	1/31/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/21/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	2/28/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/6/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/13/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/20/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	3/27/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/3/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/10/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/16/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/23/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	4/30/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/7/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/14/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement
LCS- 2D	5/21/20	N/A	14.4	235.92		N	Dedicated Transducer	PCP Installed to depth of 62' BGS, failed stator, needs replacement

				Well Total Depth				
	Date	Measured Liquid	Transducer Depth	from Top of	Elevation of	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Casing (Ft.)	Leachate	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS-3D	5/24/19	35.3	N/A	140	(1 1. 1002)	Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/31/19	37.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/7/19	39.0	N/A	140		Ŷ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/14/19	39.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/21/19	39.1	N/A	140		Ŷ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	6/28/19	39.6	N/A	140		Ŷ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/5/19	39.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/12/19	36.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/18/19	36.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	7/25/19	37.1	N/A	140		Ŷ	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/2/19	37.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/9/19	34.7	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/16/19	34.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/23/19	34.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	8/30/19	32.9	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/6/19	32.1	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/13/19	32.5	N/A	140		Ý	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/20/19	35.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	9/27/19	37.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/4/19	42.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/11/19	43.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/18/19	44.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	10/25/19	48.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/1/19	49.5	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/8/19	51.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/15/19	52.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/22/19	52.1	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	11/27/19	51.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/6/19	52.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/13/19	51.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/20/19	52.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	12/27/19	51.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/3/20	49.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/10/20	49.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/17/20	46.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/24/20	41.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	1/31/20	41.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/7/20	43.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/14/20	47.4	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/21/20	48.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	2/28/20	48.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/6/20	49.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/13/20	47.3	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/20/20	62.1	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	3/27/20	50.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/3/20	45.9	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/10/20	49.7	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/16/20	52.2	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	4/23/20	51.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/1/20	55.6	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/7/20	50.0	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/14/20	54.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually
LCS-3D	5/21/20	40.8	N/A	140		Y	Heron Dipper T	Pump operational; liquid level measured manually




	Date	Measured Liquid	Transducer Depth	Base of Sump	Pump on during		
	Reading	Level Below Ground	from Top of Casing	Elevation	measurement?		
LCS Number	Collected	Surface (ft)	(Ft.)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 4B	5/24/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/31/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/7/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/14/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/21/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	6/28/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/5/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS-4B	7/12/19	74.0	81.0	244.00	Ŷ	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/18/19	74.0	81.0	244.00	Ý	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	7/25/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/2/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/9/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/16/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/23/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	8/30/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/6/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/13/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	9/20/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	9/27/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	10/4/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0 BGS
LCS- 4B	10/11/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/18/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	10/25/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/1/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/8/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/15/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/22/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	11/29/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/6/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/13/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/20/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	12/27/19	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/3/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/17/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/24/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	1/31/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/14/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/21/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	2/28/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/6/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/13/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/20/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	3/27/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/3/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/10/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/16/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/23/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	4/30/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/7/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/14/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS
LCS- 4B	5/21/20	74.0	81.0	244.00	Y	Dedicated Transducer	Pump operational, no flow detected, liquid level >74.0' BGS

LCS-4B Liquid Level Below Ground Surface



					1				1
	Date	Measured Liquid	Transducer Height	Base of Sump		Elevation of	Pump on during		
	Reading	Level Above	above Floor of	Elevation	Height of	Leachate	measurement?		
LCS Number	Collected	Transducer (Ft.)	Quarry (Ft.)	(Ft. MSL)	Liquid (ft)	(Ft. MSL)	(Y/N)	Liquid level meter used	Comments
LCS- 5B	5/24/19	13.1	21.9	235.3	35.0	270.30	Y	Dedicated Transducer	
LCS- 5B	5/31/19	11.6	21.9	235.3	33.5	268.80	Y	Dedicated Transducer	
LCS- 5B	6/7/19	12.7	21.9	235.3	34.6	269.90	Y	Dedicated Transducer	
LCS- 5B	6/14/19	12.7	21.9	235.3	34.6	269.90	Y	Dedicated Transducer	
LCS- 5B	6/21/19	11.7	21.9	235.3	33.6	268.90	Y	Dedicated Transducer	
LCS- 5B	6/28/19	13.2	21.9	235.3	35.1	270.40	Ŷ	Dedicated Transducer	
LCS- 5B	7/5/19	12.2	21.9	235.3	34.1	269.40	Ŷ	Dedicated Transducer	
LCS- 5B	7/12/19	13.4	21.9	235.3	35.3	270.60	Ŷ	Dedicated Transducer	
LCS- 5B	7/18/19	11.6	21.9	235.3	33.5	268.80	Ŷ	Dedicated Transducer	
LCS- 5B	7/25/19	12.8	21.9	235.3	34.7	270.00	Y	Dedicated Transducer	
LCS- 5B	8/2/19	13.5	21.9	235.3	35.4	270.00	Y	Dedicated Transducer	
LCS- 5B	8/9/19	11.3	21.9	235.3	33.2	268.50	Y	Dedicated Transducer	
LCS- 5B	8/16/19	12.6	21.9	235.3	34.5	269.80	Y	Dedicated Transducer	
					34.5 34.4		Y Y		
LCS- 5B	8/23/19	12.5	21.9 21.9	235.3		269.70	Y Y	Dedicated Transducer	
LCS- 5B	8/30/19	12.3		235.3	34.2	269.50		Dedicated Transducer	
LCS- 5B	9/6/19	11.1	21.9	235.3	33.0	268.30	Y	Dedicated Transducer	
LCS- 5B	9/13/19	12.6	21.9	235.3	34.5	269.80	Y	Dedicated Transducer	
LCS- 5B	9/20/19	12.8	21.9	235.3	34.7	270.00	Y	Dedicated Transducer	
LCS- 5B	9/27/19	13.0	21.9	235.3	34.9	270.20	Y	Dedicated Transducer	
LCS- 5B	10/4/19	12.2	21.9	235.3	34.1	269.40	Y	Dedicated Transducer	
LCS- 5B	10/11/19	13.3	21.9	235.3	35.2	270.50	Y	Dedicated Transducer	
LCS- 5B	10/18/19	11.5	21.9	235.3	33.4	268.70	Y	Dedicated Transducer	
LCS- 5B	10/25/19	12.7	21.9	235.3	34.6	269.90	Y	Dedicated Transducer	
LCS- 5B	11/1/19	12.3	21.9	235.3	34.2	269.50	Y	Dedicated Transducer	
									The transducer was observed to be non-operational on 11/6/19.
LCS- 5B	11/8/19		21.9	235.3		235.30	N	Dedicated Transducer	Transducer replacement is scheduled on 11/13/19.
LCS- 5B	11/15/19		21.9	235.3		235.30	Ν	Dedicated Transducer	The transducer was observed to be non-operational on 11/6/19 and was replaced on 11/13/19. After transducer replacement, pump was non-operational due to suspected frozen forcemain section. Troubleshooting will continue the week of 11/18/19.
LCS- 5B	11/22/19	11.7	21.9	235.3	33.6	268.90	Y	Dedicated Transducer	The transducer was observed to be non-operational on 11/6/19 and was replaced on 11/13/19. After transducer replacement, pump was non-operational due to suspected frozen forcemain section. The pump and motor were replaced on 11/19/19 and LCS SB became fully operational.
LCS- 5B	11/29/19	11.0	21.9	235.3	32.9	268.20	Ý	Dedicated Transducer	
LCS- 5B	12/6/19	12.4	21.9	235.3	34.3	269.60	Ý	Dedicated Transducer	
LCS- 5B	12/13/19	12.0	21.9	235.3	33.9	269.20	Ý	Dedicated Transducer	
LCS- 5B	12/20/19	13.1	21.9	235.3	35.0	270.30	Ý	Dedicated Transducer	
LCS- 5B	12/27/19	10.0	21.9	235.3	31.9	267.20	Ŷ	Dedicated Transducer	
LCS- 5B	1/3/20	11.3	21.9	235.3	33.2	268.50	Ý	Dedicated Transducer	
LCS- 5B	1/10/20	12.4	21.9	235.3	34.3	269.60	Y	Dedicated Transducer	
LCS- 5B	1/17/20	11.3	21.9	235.3	33.2	268.50	Y	Dedicated Transducer	1
LCS- 5B LCS- 5B	1/17/20	13.0	21.9	235.3	34.9	208.50	r Y	Dedicated Transducer Dedicated Transducer	
	1/24/20	13.0	21.9	235.3	33.6	268.90	Y Y		
LCS-5B		11.7	21.9			268.90		Dedicated Transducer	
LCS-5B	2/7/20 2/14/20	12.6	21.9	235.3 235.3	34.5 34.2	269.80	Y Y	Dedicated Transducer	
LCS- 5B								Dedicated Transducer	
LCS- 5B	2/21/20	11.3	21.9	235.3	33.2	268.50	Y	Dedicated Transducer	4
LCS- 5B	2/28/20	11.6	21.9	235.3	33.5	268.80	Y	Dedicated Transducer	4
LCS- 5B	3/6/20	10.3	21.9	235.3	32.2	267.50	Y	Dedicated Transducer	
LCS- 5B	3/13/20	11.2	21.9	235.3	33.1	268.40	Y	Dedicated Transducer	
LCS- 5B	3/20/20	12.3	21.9	235.3	34.2	269.50	Y	Dedicated Transducer	
LCS- 5B	3/27/20	12.2	21.9	235.3	34.1	269.40	Y	Dedicated Transducer	
LCS- 5B	4/3/20	11.9	21.9	235.3	33.8	269.10	Y	Dedicated Transducer	
LCS- 5B	4/9/20	10.9	21.9	235.3	32.8	268.10	Y	Dedicated Transducer	
LCS- 5B	4/16/20	11.3	21.9	235.3	33.2	268.50	Y	Dedicated Transducer	
LCS- 5B	4/23/20	10.4	21.9	235.3	32.3	267.60	Y	Dedicated Transducer	
LCS- 5B	4/30/20	11.7	21.9	235.3	33.6	268.90	Y	Dedicated Transducer	
LCS- 5B	5/7/20	10.1	21.9	235.3	32.0	267.30	Y	Dedicated Transducer	
LCS- 5B	5/14/20	12.0	21.9	235.3	33.9	269.20	Ŷ	Dedicated Transducer	1
LCS- 5B	5/21/20	11.7	21.9	235.3	33.6	268.90	Ŷ	Dedicated Transducer	

LCS-5B Liquid Level Above Quarry Floor



^{*}The transducer in LCS-5B was down from 11/6/19 to 11/19/19.

Home in the state in										
(16) \cdot </td <td></td> <td>Date</td> <td></td> <td>Transducer Height</td> <td>Base of Sump</td> <td></td> <td>Elevation of</td> <td>Pump on during</td> <td></td> <td></td>		Date		Transducer Height	Base of Sump		Elevation of	Pump on during		
GG 0 Set 00 Set 00 <td></td>										
CCS 80 PD/19 R31 FA 4432 FB 44600 V Decided Transact CCS 80 PC/19 6.4 4932 100 4400 V Decided Transact CCS 80 PC/19 6.5 4.4 4932 100 4400 V Decided Transact CCS 80 PC/19 6.5 4.4 4932 100 4400 V Decided Transact CCS 80 PC/19 6.5 4.4 4932 V Decided Transact Decided Transact CCS 80 PC/19 6.3 4.4 4932 V Decided Transact Decided Transact CCS 80 PC/19 6.4 4932 441.6 V Decided Transact Decided Transact CCS 80 PC/19 6.4 4932 441.7 V Decided Transact Decided Transact CCS 80 PC/19 6.4 4932 441.7 V Decided Transact Decided Transact CCS 80 PC/19 6.4										Comments
Color 977 134 144 420 450 470 Decided [masker] Color 103 144 443 440 440 V Decided [masker] Color 103 104 443 443 V Decided [masker] Color 103 104 443 V Decided [m										
(55.68 61/07 0.32 6.4 45.8 15.8 440.2 Y Decked Transform (10.68 7.071 0.3 0.4 45.9										
Lics. 68 92/10 3.6 4.6 4.8.0 8.0 4.6.0 Y Declarating impacts Lics. 68 9.60 1.3 4.6 4.8.0 4.6.0 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
LCS.48 OPER Top PLA OPER Top Descent Transform LCS.48 OPER 100 14 OPER Top Descent Transform LCS.48 OPER 107 0.4 OPER OPER Top Descent Transform LCS.48 OPER 0.7 0.4 OPER										
LG5.68 70% 8.4 9.4 69.9 18.8 448.9 Y Designat fundace LG5.68 70.19 0.3 0.4 452.2 1.9 0.4 </td <td></td>										
LCS 68 P7/218 0.03 9.4 4652 1.97 4652 Y Designed Frankder LCS 68 P7/18 0.5 9.4 4253 18.1 446.2 Y Designed Frankder LCS 68 P7/18 0.5 9.4 4253 18.4 447.92 Y Designed Frankder LCS 68 P0/18 0.5 9.4 4253 18.4 447.92 Y Designed Frankder LCS 68 P0/18 0.5 9.4 4253 18.4 447.2 Y Designed Frankder LCS 68 P0/18 0.5 9.4 4253 18.3 447.2 Y Designed Frankder LCS 68 P0/18 0.5 9.4 4253 18.3 444.2 Y Designed Frankder LCS 68 P0/18 0.5 9.4 4253 18.3 446.2 Y Designed Frankder LCS 68 P0/18 0.5 9.4 4253 18.3 446.2 Y Designed Fran										
Liss and TYRE 9 4.4 4932 9 1 4480 Y Destination Transacce Liss and 77370 3 3 4.4 4032 Y Destination Transacce Liss and 77370 3 3 4.4 4032 Y Destination Transacce Liss and 77710 3.6 4.4 4032 Y Destination Transacce Liss and 77710 3.6 4.4 4032 Y Destination Transacce Liss and 77710 3.6 4.4 4032 Y Destination Transacce Liss and 77718 9.7 4.4 4032 Y Destination Transacce Liss and 77718 9.7 4.4 4032 Y Destination Transacce Liss and 77718 9.7 4.4 4032 Y Destination Transacce Liss and 77718 9.7 4.4 4032 Y Destination Transacce Liss andift frame data										
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$										
LGS-68 6/30 9.3 9.4 49.32 18.4 47.22 Y Deduced Transboor LGS-68 6/010 10.2 9.4 40.32 10.3 44.32 Y Deduced Transboor LGS-68 6/010 10.2 9.4 40.32 10.3 44.32 Y Deduced Transboor LGS-68 6/010 10.3 4.4 40.32 Y Deduced Transboor LGS-68 6/010 10.3 4.4 40.32 Y Deduced Transboor LGS-68 6/0110 9.4 40.32 10.5 44.602 Y Deduced Transboor LGS-68 10/118 9.4 4.4 40.32 10.4 Deduced Transboor LGS-68 10/118 9.4 4.4 40.32 Y Deduced Transboor LGS-68 10/118 9.4 4.4 40.32 Y Deduced Transboor LGS-68 10/118 9.4 40.32 18.4 44.62 Y Deduced Transboor										
LCS-68 W19 10.7 6.4 49.92 201 Add 202 V Decidant Transform LCS-68 W19 6.3 6.4 40.92 16.3 40.92 V Decidant Transform LCS-68 W19 6.5 6.4 40.92 16.3 40.92 V Decidant Transform LCS-68 W19 6.5 6.4 40.92 16.3 40.92 V Decidant Transform LCS-68 W19 6.5 6.4 40.92 16.3 40.92 V Decidant Transform LCS-68 W19 0.4 40.92 V Decidant Transform Decidant Transform LCS-68 10.919 1.0 6.4 40.92 V Decidant Transform LCS-68 10.919 0.7 6.4 40.92 V Decidant Transform LCS-68 10.919 0.3 6.4 40.92 V Decidant Transform LCS-68 10.919 0.3 6.4 40.92 V </td <td></td>										
LGS-88 97191 9.3 9.4 49.22 19.3 448.82 Y Poteolation Transition LGS-88 67079 1.2 9.4 49.32 1.0										
LC6.48 62319 0.02 9.4 49.92 19.4 449.12 Y Obcided Transform LC5.48 60319 6.3 9.4 425.2 15.2 417.2 Y Dedicable Transform LC5.48 60319 0.1 9.4 425.2 15.9 449.2 Y Dedicable Transform LC5.48 60319 0.1 9.4 425.2 15.1 448.2 Y Dedicable Transform LC5.48 60319 0.1 9.4 425.2 15.1 448.2 Y Dedicable Transform LC5.48 107479 0.0 9.4 425.2 15.1 448.2 Y Dedicable Transform LC5.48 107479 0.5 9.4 425.2 15.3 448.2 Y Dedicable Transform LC5.48 107479 0.5 9.4 425.2 15.3 448.2 Y Dedicable Transform LC5.48 117279 0.5 9.4 425.2 15.3 448.2 Y										
LG6.8 40019 4.8 9.4 49.92 18.2 447.72 V Objecting Translater LG5.86 6.910 5.5 9.4 429.2 10.8 449.2 V Decisited Translater LG5.86 6.2799 6.7 9.4 429.2 10.8 449.2 V Decisited Translater LG5.86 6.2799 6.7 9.4 429.2 19.8 448.2 V Decisited Translater LG5.86 6.9479 9.7 9.4 429.2 19.8 448.2 V Decisited Translater LG5.86 10.9719 9.7 9.4 429.2 19.8 449.2 V Decisited Translater LG5.86 10.9719 9.7 9.4 429.2 19.8 449.2 V Decisited Translater LG5.86 10.9719 9.3 9.4 429.2 19.8 449.2 V Decisited Translater LG5.86 10.9719 9.3 9.4 429.2 V Decisited Transla										
LGS-80 98/19 9.6 9.4 4/29.27 7.8 444.22 Y Deficial Transdoor LGS-80 92/19 0.5 0.4 4/29.27 Y Deficial Transdoor LGS-80 92/19 0.7 0.4 4/29.27 Y Deficial Transdoor LGS-80 10/11/9 0.4 4/29.27 Y Deficial Transdoor LGS-80 10/11/9 0.4 4/29.27 10.1 4/49.27 Y Deficial Transdoor LGS-80 10/11/9 0.4 4/29.27 10.1 4/49.27 Y Deficial Transdoor LGS-80 10/11/9 0.4 4/29.27 10.1 4/49.27 Y Deficial Transdoor LGS-80 11/19/1 0.4 4/29.27 10.2 Deficial Transdoor LGS-80 11/29/1 0.5 0.4 4/29.27 Y Deficial Transdoor LGS-80 11/29/1 0.5 0.4 4/29.2 Y Deficial Transdoor LGS-80 11/29/1 <										
LCS-68 P1738 10.5 6.4 429.25 19.8 440.42 Y Decident Transdoor LCS-68 20019 0.1 6.4 642.92 10.5 464.92 Y Decident Transdoor LCS-68 101179 9.4 64.9 22.9 10.5 464.92 Y Decident Transdoor LCS-68 101179 9.4 64.4 629.2 10.5 464.92 Y Decident Transdoor LCS-68 101179 0.1 6.4 429.22 10.5 449.92 Y Decident Transdoor LCS-68 111917 5.5 6.4 429.22 10.5 449.92 Y Decident Transdoor LCS-68 119171 5.5 6.4 429.22 10.5 449.92 Y Decident Transdoor LCS-68 119171 10.4 429.22 10.5 449.92 Y Decident Transdoor LCS-68 119201 0.4 429.22 10.5 449.92 Y Decident Transd										
LGS-68 92019 10.1 9.4 429.22 15.5 440.02 Y Dedicated Transdoor LGS-68 192119 9.4 429.22 15.1 448.22 Y Dedicated Transdoor LGS-68 191110 9.4 429.22 19.4 448.22 Y Dedicated Transdoor LGS-68 191110 9.4 429.22 19.4 448.22 Y Dedicated Transdoor LGS-68 191110 9.4 429.22 19.8 448.22 Y Dedicated Transdoor LGS-68 119191 9.5 9.4 429.22 19.8 448.22 Y Dedicated Transdoor LGS-68 119291 9.6 9.4 429.22 19.8 448.72 Y Dedicated Transdoor LGS-68 129219 8.1 429.22 19.8 449.12 Y Dedicated Transdoor LGS-68 129179 8.3 4.4 429.22 19.8 449.12 Y Dedicated Transdoor LGS-68										
LCS 68 027/16 9.7 9.4 428.02 18.1 448.62 Y Decidated Transduerr LCS 68 101/16 8.0 9.4 403.02 18.3 448.62 Y Decidated Transduerr LCS 68 100/176 8.0 9.4 403.02 18.3 448.22 Y Decidated Transduerr LCS 68 100/176 8.0 9.4 403.02 18.1 448.62 Y Decidated Transduerr LCS 68 100/071 9.0 4.4 409.52 18.1 448.62 Y Decidated Transduerr LCS 68 110/210 9.8 9.4 409.52 18.3 448.62 Y Decidated Transduerr LCS 68 110/210 9.8 9.4 409.52 18.3 448.22 Y Decidated Transduerr LCS 68 120/19 9.8 9.4 429.52 18.5 448.22 Y Decidated Transduerr LCS 68 110/20 9.4 429.52 18.5 448.22										
LCS-86 104/19 9.8 9.4 429.22 19.3 448.82 Y Dedicated Transduer LCS-86 101/19 0.4 428.22 19.4 448.82 Y Dedicated Transduer LCS-86 101/19 0.3 0.4 428.22 19.4 448.82 Y Dedicated Transduer LCS-86 101/19 9.1 0.4 428.22 19.3 448.82 Y Dedicated Transduer LCS-86 11/19/19 9.5 9.4 428.22 19.3 448.82 Y Dedicated Transduer LCS-86 11/19/19 9.5 9.4 428.22 19.2 448.82 Y Dedicated Transduer LCS-86 11/20/19 0.4 428.22 19.2 448.82 Y Dedicated Transduer LCS-86 12/20/19 0.1 0.4 428.22 19.2 448.92 Y Dedicated Transduer LCS-86 11/20/19 0.1 0.4 429.22 10.8 448.12 Y										
LCS-88 191119 9.4 9.4 42.52 118.8 44.3.22 Y Dedicated Transdoor LCS-88 100/113 0.0 6.4 420.52 116.4 443.92 Y Dedicated Transdoor LCS-88 100/113 0.0 6.4 420.52 110.4 443.92 Y Dedicated Transdoor LCS-88 11/19/19 9.7 6.4 420.52 110.4 448.92 Y Dedicated Transdoor LCS-86 11/19/19 9.7 6.4 420.52 118.2 448.92 Y Dedicated Transdoor LCS-86 11/19/19 0.5 6.4 420.52 118.2 448.92 Y Dedicated Transdoor LCS-86 12/2119 0.14 6.4 420.52 118.6 449.92 Y Dedicated Transdoor LCS-86 11/200 0.4 420.52 118.6 449.12 Y Dedicated Transdoor LCS-86 11/120 0.4 420.52 118.6 449.12 Y										
LCS-68 109/879 10.0 0.4 429.02 119.4 448.02 Y Decleaded Translucer LCS-68 10/0791 0.7 0.4 429.52 16.1 448.62 Y Decleaded Translucer LCS-68 10/079 0.3 0.4 429.52 16.3 448.62 Y Decleaded Translucer LCS-68 11/079 0.3 0.4 429.52 16.3 448.72 Y Decleaded Translucer LCS-68 11/0291 0.8 0.4 429.52 16.3 448.72 Y Decleaded Translucer LCS-68 11/0291 0.8 0.4 429.52 16.5 448.02 Y Decleaded Translucer LCS-68 12/2919 0.1 0.4 429.52 16.5 448.02 Y Decleaded Translucer LCS-68 12/2919 0.1 0.4 429.52 16.5 448.02 Y Decleaded Translucer LCS-68 11/700 0.2 0.4 429.52 16.5										
LGS-68 102919 9.7 9.4 429.22 101 44.8.02 Y Decision Transdoor LGS-68 11/170 0.1 0.4 429.22 103 44.0.2 Y Decision Transdoor LGS-68 11/070 0.5 0.4 429.22 103 44.0.2 Y Decision Transdoor LGS-68 11/070 0.4 429.22 103 44.0.2 Y Decision Transdoor LGS-68 11/0219 0.4 429.22 10.8 44.0.2 Y Decision Transdoor LGS-68 11/0219 0.4 429.22 10.8 44.0.2 Y Decision Transdoor LGS-68 11/020 0.4 429.22 10.5 44.0.2 Y Decision Transdoor LGS-68 11/020 0.4 429.22 10.5 44.0.2 Y Decision Transdoor LGS-68 11/020 0.4 429.22 10.5 44.0.2 Y Decision Transdoor LGS-68 11/020					429.52					
LCS-86 11/1/19 10.1 9.4 42952 19.5 44802 Y Dedicated Transduce LCS-86 11/15/19 9.6 9.4 42952 18.3 448.42 Y Dedicated Transduce LCS-86 11/15/19 9.6 9.4 42952 18.3 448.42 Y Dedicated Transduce LCS-86 12/02/19 9.6 44.2252 18.8 446.22 Y Dedicated Transduce LCS-86 12/21/19 9.1 9.4 42952 18.6 448.02 Y Dedicated Transduce LCS-86 12/20/19 9.1 9.4 42952 18.6 448.02 Y Dedicated Transduce LCS-86 12/20/19 9.1 9.4 42952 18.5 448.02 Y Dedicated Transduce LCS-86 10/200 0.1 9.4 42952 18.5 448.02 Y Dedicated Transduce LCS-86 10/200 0.4 42952 18.5 448.02 Y										
LCS-68 11/8719 9.9 9.4 429.52 11.3 44.8.2 Y Deckated Transduor LCS-68 11/2719 9.6 9.4 429.52 11.9 V Deckated Transduor LCS-68 11/2219 9.6 9.4 429.52 11.6 44.87.2 Y Deckated Transduor LCS-68 11/2219 9.4 429.52 11.6 44.61.2 Y Deckated Transduor LCS-68 12/2019 9.1 9.4 429.52 11.6 44.61.2 Y Deckated Transduor LCS-68 12/2019 9.1 9.4 429.52 11.6 448.2 Y Deckated Transduor LCS-68 12/2019 9.1 9.4 429.52 11.6 448.12 Y Deckated Transduor LCS-68 11/920 9.4 429.52 11.8 448.12 Y Deckated Transduor LCS-68 11/920 9.4 429.52 11.8 448.12 Y Deckated Transduor										
LCS-68 11/15/19 9.5 9.4 4429.52 16.9 444.42 Y Dedicated Transduer LCS-68 11/2010 9.8 9.4 449.52 16.2 447.72 Y Dedicated Transduer LCS-68 11/2010 8.9 9.4 449.52 17.9 V Dedicated Transduer LCS-68 11/2010 8.9 9.4 449.52 17.9 V Dedicated Transduer LCS-68 12/2010 9.1 9.4 449.52 18.6 446.12 Y Dedicated Transduer LCS-68 19/201 0.1 9.4 429.52 18.6 446.12 Y Dedicated Transduer LCS-68 19/200 0.4 429.52 1.6 446.12 Y Dedicated Transduer LCS-68 11/200 0.4 429.52 1.6 446.12 Y Dedicated Transduer LCS-68 11/200 0.4 429.52 1.6 N Dedicated Transduer LCS-68 11/200										
LCS-68 1172/19 9.8 9.4 4429.52 19.2 448.72 Y Dedicated Transducer LCS-68 1172/19 6.9 9.4 429.52 16.3 447.82 Y Dedicated Transducer LCS-68 12/19 10.2 6.4 429.52 16.3 447.82 Y Dedicated Transducer LCS-68 12/21/9 0.3 6.4 429.52 16.8 440.12 Y Dedicated Transducer LCS-68 12/27/9 0.3 6.4 429.52 17.9 440.22 Y Dedicated Transducer LCS-68 11/220 9.2 9.4 429.52 18.6 441.2 Y Dedicated Transducer LCS-68 11/120 0.4 429.52 18.6 449.12 Y Dedicated Transducer LCS-68 11/120 0.4 429.52 18.6 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1173/20. Transduce replacement LCS-68 11/120 9.4 429.52										
LCS-68 11/2019 8.9 9.4 429.22 18.3 447.82 Y Decidated Transducer LCS-68 12/2019 10.4 9.4 429.52 19.6 448.02 Y Decidated Transducer LCS-68 12/2019 0.1 9.4 429.52 19.6 448.02 Y Decidated Transducer LCS-68 12/2019 0.1 9.4 429.52 19.6 448.02 Y Decidated Transducer LCS-68 11/2019 0.1 9.4 429.52 19.6 448.02 Y Decidated Transducer LCS-68 11/1700 9.4 429.52 19.6 448.02 Y Decidated Transducer LCS-68 11/1700 9.4 429.52 N Decidated Transducer The LCS-68 transducer was observed to be non-operational on 11/320. Transducer replacement is pending replacement parts arrival. LCS-68 13120 9.4 429.52 N Decidated Transducer LCS-68 27/20 9.4 429.52 N Decidated Transducer repla										
LCS-68 12919 10.4 9.4 429.52 19.8 449.32 Y Decidate Transduer LCS-68 127319 0.1 9.4 429.52 19.6 448.12 Y Decidate Transduer LCS-68 122719 0.3 9.4 429.52 18.5 448.02 Y Decidate Transduer LCS-68 11720 0.4 429.52 18.5 448.02 Y Decidate Transduer LCS-68 11720 9.4 429.52 18.6 448.02 Y Decidate Transduer LCS-68 11720 9.4 429.52 18.6 448.02 Y Decidate Transduer LCS-68 11720 9.4 429.52 18.6 449.02 Y Decidate Transduer LCS-68 17270 9.4 429.52 18.6 N Decidate Transduer The LCS-68 transduer was observed to to no-operational on 11/320. Transduer replacement is pending replacement parts arrival. LCS-68 17270 9.4 429.52 16.7 N Declate T									Dedicated Transducer	
LCS-68 12/379 10.2 9.4 429.2 19.6 44412 Y Dedicated Transducer LCS-68 12/2019 9.1 9.4 429.52 18.5 448.02 Y Dedicated Transducer LCS-68 12/2719 9.3 9.4 429.52 18.5 448.02 Y Dedicated Transducer LCS-68 1/1/20 9.4 429.52 18.5 448.02 Y Dedicated Transducer LCS-68 1/1/20 9.4 429.52 18.5 448.12 Y Dedicated Transducer LCS-68 1/1/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement to the inno-operational on 1/1320. Transducer replacement to th									Dedicated Transducer	
LCS-68 122019 9.1 9.4 429.52 18.5 448.02 Y Dedicated Transducer LCS-68 17207 9.3 9.4 429.52 18.5 448.02 Y Dedicated Transducer LCS-68 17020 9.2 9.4 429.52 18.5 448.12 Y Dedicated Transducer LCS-68 11720 9.4 429.52 18.5 448.12 Y Dedicated Transducer LCS-68 11720 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 117320. Transducer replacement is pending replacement parts arrival. LCS-68 17270 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 117320. Transducer replacement is pending replacement parts arrival. LCS-68 27720 9.4 429.52 N Dedicated Transducer LCS-68 21/420 9.4 429.52 27.8 457.32 N Dedicated Transducer LCS-68 22/120 NA NA 429.		12/6/19						Y	Dedicated Transducer	
LCS-68 122719 9.3 9.4 429.52 18.7 448.22 Y Dedicated Transducer LCS-68 11/020 9.2 9.4 429.52 18.6 448.12 Y Dedicated Transducer LCS-68 11/020 9.2 9.4 429.52 N Dedicated Transducer LCS-68 11/120 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement parts atrival. LCS-68 11/12/0 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement is pending replacement parts atrival. LCS-68 1/24/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement is pending replacement parts atrival. The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement is pending replacement parts atrival. The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement is pending replacement parts atrival. The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement is pending replacement parts atrival. The LCS-68 transducer was observed to be non-operational on 1/1320. Transducer replacement is pending replac								Y	Dedicated Transducer	
LCS-6B 1//20 10.1 9.4 429.52 18.6 448.12 Y Dedicated Transducer LCS-6B 1/1020 9.2 9.4 429.52 18.6 448.12 Y Dedicated Transducer The LCS-8B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 1/12/20 9.4 429.52 N Dedicated Transducer The LCS-8B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 1/24/20 9.4 429.52 N Dedicated Transducer The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 1/31/20 9.4 429.52 N Dedicated Transducer The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 2/14/20 9.4 429.52 N Dedicated Transducer The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 2/14/20 9.4 429.52 27.8 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20.		12/20/19						Y	Dedicated Transducer	
LCS-68 1/1/20 9.2 9.4 429.52 18.6 448.12 Y Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 1/17/20 9.4 429.52 N N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 1/12/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 1/12/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/1/20 9.4 429.52 N N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/14/20 9.4 429.52 27.8 457.32 N Heron Dipper T The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-68 2/2/200 N/A N/A 42	LCS- 6B	12/27/19	9.3	9.4	429.52	18.7	448.22	Y		
LCS-68 11/120 9.4 429.52 N Dedicated Transducer vas observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-68 1/24/20 9.4 429.52 N Dedicated Transducer vas observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-68 1/31/20 9.4 429.52 N Dedicated Transducer vas observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-68 2/17/20 9.4 429.52 N Dedicated Transducer vas observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-68 2/11/20 9.4 429.52 N N Dedicated Transducer vas observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-68 2/11/20 N/A N/A 429.52 27.8 457.32 N Heron Dipper T The LCS-68 transducer vas observed to be non-operational on 1/13/20. Transducer replacement is tentatively scheduled the week of 39/20. Liquid level was measured manually. LCS-68 2/28/20 N/A N/A 429.52 28.3 457.82 N Heron Dipper T<								Y		
LCS-6B 1/17/20 9.4 429.52 N Dedicated Transducer microsoft microsoft <thmicrosoft< th=""> microsoft microsoft<</thmicrosoft<>	LCS- 6B	1/10/20	9.2	9.4	429.52	18.6	448.12	Y	Dedicated Transducer	
LCS-68 1/24/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 1/31/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/17/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/14/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/21/20 NA N/A 429.52 27.8 457.32 N Heron Dipper T The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/22/20 NA N/A 429.52 28.3 457.82 N Heron Dipper T The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 3/16/20 NA N/A 429.52 21.8 457	LCS-6B	1/17/20		9.4	429.52			N	Dedicated Transducer	
LCS-68 1/31/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/1/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/14/20 9.4 429.52 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/14/20 9.4 429.52 27.8 N Dedicated Transducer The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/21/20 N/A N/A 429.52 27.8 457.32 N Heron Dipper T The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement parts arrival. LCS-68 2/21/20 N/A N/A 429.52 28.3 457.82 N Heron Dipper T The LCS-68 transducer was observed to be non-operational on 1/13/20. Transducer replacement is tentitively schedulet the week of 3/9/20. Liquid level was measured manually. LCS-68 3/6/20 N/										The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS-6B 2/7/20 9.4 429.52 N Dedicated Transducer The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement LCS-6B 2/14/20 9.4 429.52 N Dedicated Transducer LCS-6B 2/14/20 9.4 429.52 N Dedicated Transducer LCS-6B 2/21/20 N/A N/A 429.52 27.8 457.32 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. Liquid level was measured manually. LCS-6B 2/21/20 N/A N/A 429.52 28.3 457.82 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. Liquid level was measured manually. LCS-6B 3/620 N/A N/A 429.52 28.0 457.52 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. Liquid level was measured manually. LCS-6B 3/620 N/A N/A 429.52 28.0 457.52 N										The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement
LCS-6B 2/14/20 9.4 429.52 N Dedicated Transducer The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 2/21/20 N/A N/A 429.52 27.8 457.32 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. LCS-6B 2/28/20 NA N/A 429.52 28.0 457.82 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. Transducer vas observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is transducer LCS-6B 3/13/20 12.5 9.4 429.52										
LCS- 6B 2/21/20 N/A N/A V/A V/A V/A 429.52 27.8 457.32 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is pending replacement parts arrival. Liquid level was measured manually. LCS- 6B 2/28/20 N/A N/A 429.52 28.3 457.82 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is scheduled fro 3/11/20. Liquid level was measured manually. LCS- 6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is scheduled for 3/11/20. Liquid level was measured manually. LCS- 6B 3/13/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer 0.3/13/20. Liquid level was measured manually. LCS- 6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer 0.3/13/20. LCS-6B became fully operational 0.3/13/20. LCS- 6B 3/27/20 11.5 9.4 429.52 21.4	LCS- 6B	2/7/20		9.4	429.52			N	Dedicated Transducer	
LCS-6B 2/21/20 N/A N/A 429.52 27.8 457.32 N Heron Dipper T is pending replacement parts arrival. Liquid level was measured manually. LCS-6B 2/28/20 N/A N/A 429.52 28.3 457.82 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is tentiatively scheduled the week of 3/9/20. Liquid level was measured manually. LCS-6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is tentiatively scheduled for 3/11/20. Liquid level was measured manually. LCS-6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is tentiatively schedule dor 3/11/20. Liquid level was measured manually. LCS-6B 3/13/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer CS-6B pump was observed to be non-operational on 3/13/20. LCS-6B 3/20/20 11.9 9.4 429.52 21.3 4	LCS- 6B	2/14/20		9.4	429.52			N	Dedicated Transducer	
LCS-6B 2/28/20 N/A N/A 429.52 28.3 457.82 N Heron Dipper T is tentatively scheduled the week of 3/9/20. Liquid level was measured manually. LCS-6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T is tentatively scheduled the week of 3/9/20. Liquid level was measured manually. LCS-6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T is tentatively scheduled the week of 3/9/20. Liquid level was measured manually. LCS-6B 3/13/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer on 3/13/20. LCS-6B became fully operational on 3/13/20. LCS-6B 3/20/20 12.3 9.4 429.52 21.9 451.42 Y Dedicated Transducer LCS-6B 3/20/20 11.5 9.4 429.52 21.9 450.42 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B	LCS- 6B	2/21/20	N/A	N/A	429.52	27.8	457.32	N	Heron Dipper T	
LCS-6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T The LCS-6B transducer was observed to be non-operational on 1/13/20. Transducer replacement is scheduled for 3/11/20. Liquid level was measured manually. LCS-6B 3/6/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer The LCS-6B transducer was replaced on 3/11/20. Cliquid level was measured manually. LCS-6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer on 3/13/20. LCS-6B transducer was replaced on 3/11/20. and the pump became fully operational. The LCS-6B transducer LCS-6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer on 3/13/20. LCS-6B became fully operational on 3/13/20. LCS-6B 3/27/20 11.9 9.4 429.52 21.3 450.82 Y Dedicated Transducer 0.3/13/20. LCS-6B transducer 0.3/13/20. LCS-6B transducer LCS-6B 4/3/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer dedicated Transducer dedicated Transd		2/28/20	N//A	N//A	400.50	20.2	457.00	N	Llaran Dinnan T	
LCS-6B 3/6/20 N/A N/A 429.52 28.0 457.52 N Heron Dipper T is scheduled for 3/11/20. Liquid level was measured manually. LCS-6B 3/13/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer The LCS-6B transducer was observed to be non-operational on 3/12/2. Inc LCS-6B became fully operational on 3/12/2. Inc LCS-6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer on 3/13/20. LCS-6B became fully operational on 3/12/20. Inc LCS-6B became fully operational on 3/12/20. Inc LCS-6B 3/20/20 11.5 9.4 429.52 21.3 450.82 Y Dedicated Transducer Inc Soc 6B 4/3/20 11.5 9.4 429.52 21.4 450.92 Y Dedicated Transducer Inc Soc 6B 4/10/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer Inc Soc 6B Inc Soc 6B 4/10/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer Inc Soc 6B VED was observed to be non-operational on 4/23/20. The VFD was replaced on 4/23/20. The VFD was replaced on 4/23/20. The VF	L00-0B	2120120	IN/A	IN/A	423.02	20.0	401.02	IN	Lielou nibhei I	
LCS-6B 3/13/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer The LCS-6B transducer was replaced on 3/11/20 and the pump became fully operational. The LCS-6B pump was observed to be non-operational on 3/12/20. The LCS-6B pump was replaced on 3/13/20. LCS-6B became fully operational on 3/13/20. LCS-6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer on 3/13/20. LCS-6B became fully operational on 3/13/20. LCS-6B 3/20/20 11.9 9.4 429.52 21.3 450.82 Y Dedicated Transducer LCS-6B 4/3/20 11.5 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/10/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/10/20 12.4 9.4 429.52 12.8 451.32 Y Dedicated Transducer LCS-6B 4/16/20 <td>LCS AP</td> <td>2/6/20</td> <td>N/A</td> <td>NI/A</td> <td>420 E2</td> <td>28.0</td> <td>457.50</td> <td>N</td> <td></td> <td></td>	LCS AP	2/6/20	N/A	NI/A	420 E2	28.0	457.50	N		
LCS-6B 3/13/20 12.5 9.4 429.52 21.9 451.42 Y Dedicated Transducer on 3/13/20. LCS-6B became fully operational on 3/13/20. LCS-6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer LCS-6B 3/20/20 11.9 9.4 429.52 21.3 450.82 Y Dedicated Transducer LCS-6B 4/3/20 11.5 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/10/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/10/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 12.4 9.4 429.52 18.3 447.82 Y Dedicated Transducer	LCO- 0B	3/0/20	IN/A	N/A	429.52	∠0.U	437.52	N	петоп Dipper 1	The LCS-6B transducer was replaced on 3/11/20 and the pump became fully operational. The
LCS-6B 3/20/20 12.3 9.4 429.52 21.7 451.22 Y Dedicated Transducer LCS-6B 3/27/20 11.9 9.4 429.52 21.3 450.82 Y Dedicated Transducer LCS-6B 4/3/20 11.5 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B 4/3/20 12.0 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/71/20 9.0										
LCS-6B 3/27/20 11.9 9.4 429.52 21.3 450.82 Y Dedicated Transducer LCS-6B 4/3/20 11.5 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer LCS-6B 4/10/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/10/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/14/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/14/20 13.3										on 3/13/20. LCS-6B became fully operational on 3/13/20.
LCS-6B 4/3/20 11.5 9.4 429.52 20.9 450.42 Y Dedicated Transducer LCS-6B 4/10/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/7/20 9.0 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/7/4/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer										
LCS-6B 4/10/20 12.0 9.4 429.52 21.4 450.92 Y Dedicated Transducer LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/71/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/71/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/71/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/71/20 9.0 9.4 429.52 22.7 452.22 Y Dedicated Transducer										
LCS-6B 4/16/20 12.4 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 9.4 429.52 21.8 451.32 Y Dedicated Transducer LCS-6B 4/23/20 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/17/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/14/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer										
LCS-6B 4/23/20 9.4 429.52 18.3 447.82 Y Dedicated Transducer The LCS-6B VFD was observed to be non-operational on 4/23/20. The VFD was replaced on 4/23/20. The VFD was rep										
LCS-6B 4/23/20 M 4/29.52 M Y Dedicated Transducer 4/23/20 and LCS-6B became fully operational. A level sensor reading was not collected during the weekly reporting period due to VFD communication loss with the site's SCADA system. LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/7/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/14/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer	LCS- 6B	4/16/20	12.4	9.4	429.52	21.8	451.32	Y	Dedicated Transducer	
LCS-6B 4/23/20 9.4 429.52 Y Dedicated Transducer weekly reporting period due to VFD communication loss with the site's SCADA system. LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/7/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/14/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer										
LCS-6B 4/30/20 8.9 9.4 429.52 18.3 447.82 Y Dedicated Transducer LCS-6B 5/7/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/7/4/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer	LCS- 6B	4/23/20		9.4	429.52			Y	Dedicated Transducer	
LCS-6B 5/7/20 9.0 9.4 429.52 18.4 447.92 Y Dedicated Transducer LCS-6B 5/14/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer			8.9			18.3	447.82	Y		
LCS-6B 5/14/20 13.3 9.4 429.52 22.7 452.22 Y Dedicated Transducer										
	LCS- 6B	5/21/20	13.3	9.4	429.52	22.7	452.22		Dedicated Transducer	