

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-14R	4/26/2016	20	168.4	479	
TMP-14R	4/26/2016	40	197.9	459	
TMP-14R	4/26/2016	60	199.7	439	
TMP-14R	4/26/2016	80	192.4	419	
TMP-14R	4/26/2016	100	182.4	399	
TMP-14R	4/26/2016	120	176.8	379	
TMP-14R	4/26/2016	140	172.6	359	
TMP-14R	5/2/2016	20	166.9	479	
TMP-14R	5/2/2016	40	196.9	459	
TMP-14R	5/2/2016	60	199.0	439	
TMP-14R	5/2/2016	80	191.7	419	
TMP-14R	5/2/2016	100	181.7	399	
TMP-14R	5/2/2016	120	176.2	379	
TMP-14R	5/2/2016	140	172.1	359	
TMP-14R	5/9/2016	20	165.5	479	
TMP-14R	5/9/2016	40	195.9	459	
TMP-14R	5/9/2016	60	198.0	439	
TMP-14R	5/9/2016	80	191.0	419	
TMP-14R	5/9/2016	100	180.7	399	
TMP-14R	5/9/2016	120	175.4	379	
TMP-14R	5/9/2016	140	171.2	359	
TMP-14R	5/18/2016	20	166.4	479	
TMP-14R	5/18/2016	40	197.0	459	
TMP-14R	5/18/2016	60	199.2	439	
TMP-14R	5/18/2016	80	192.4	419	
TMP-14R	5/18/2016	100	182.0	399	
TMP-14R	5/18/2016	120	176.6	379	
TMP-14R	5/18/2016	140	172.5	359	
TMP-14R	5/23/2016	20	167.3	479	
TMP-14R	5/23/2016	40	197.9	459	
TMP-14R	5/23/2016	60	200.0	439	
TMP-14R	5/23/2016	80	193.9	419	
TMP-14R	5/23/2016	100	183.1	399	
TMP-14R	5/23/2016	120	177.8	379	
TMP-14R	5/23/2016	140	173.8	359	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-19	4/26/2016	20	195.3	473	
TMP-19	4/26/2016	40		453	[not reliable - connectivity test 06/12/2015]
TMP-19	4/26/2016	60	237.5	433	
TMP-19	4/26/2016	80	250.1	413	
TMP-19	4/26/2016	120		373	[not reliable - connectivity test 06/12/2015]
TMP-19	4/26/2016	140		353	[not reliable - connectivity test 06/12/2015]
TMP-19	5/2/2016	20	194.2	473	
TMP-19	5/2/2016	40		453	[not reliable - connectivity test 06/12/2015]
TMP-19	5/2/2016	60	236.5	433	
TMP-19	5/2/2016	80	249.1	413	
TMP-19	5/2/2016	120		373	[not reliable - connectivity test 06/12/2015]
TMP-19	5/2/2016	140		353	[not reliable - connectivity test 06/12/2015]
TMP-19	5/9/2016	20	194.1	473	
TMP-19	5/9/2016	40		453	[not reliable - connectivity test 06/12/2015]
TMP-19	5/9/2016	60	236.7	433	
TMP-19	5/9/2016	80	249.3	413	
TMP-19	5/9/2016	120		373	[not reliable - connectivity test 06/12/2015]
TMP-19	5/9/2016	140		353	[not reliable - connectivity test 06/12/2015]
TMP-19	5/18/2016	20	192.7	473	
TMP-19	5/18/2016	40		453	[not reliable - connectivity test 06/12/2015]
TMP-19	5/18/2016	60	236.6	433	
TMP-19	5/18/2016	80	248.9	413	
TMP-19	5/18/2016	120		373	[not reliable - connectivity test 06/12/2015]
TMP-19	5/18/2016	140		353	[not reliable - connectivity test 06/12/2015]
TMP-19	5/23/2016	20	193.9	473	
TMP-19	5/23/2016	40		453	[not reliable - connectivity test 06/12/2015]
TMP-19	5/23/2016	60	237.4	433	
TMP-19	5/23/2016	80	249.7	413	
TMP-19	5/23/2016	120		373	[not reliable - connectivity test 06/12/2015]
TMP-19	5/23/2016	140		353	[not reliable - connectivity test 06/12/2015]

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-20	4/26/2016	20	152.7	478	
TMP-20	4/26/2016	40	220.8	458	
TMP-20	4/26/2016	60	242.7	438	
TMP-20	4/26/2016	80	256.1	418	
TMP-20	4/26/2016	100	266.8	398	
TMP-20	4/26/2016	120	273.1	378	
TMP-20	4/26/2016	140	273.9	358	
TMP-20	5/2/2016	20	152.9	478	
TMP-20	5/2/2016	40	221.2	458	
TMP-20	5/2/2016	60	242.5	438	
TMP-20	5/2/2016	80	255.9	418	
TMP-20	5/2/2016	100	266.7	398	
TMP-20	5/2/2016	120	273.2	378	
TMP-20	5/2/2016	140	273.9	358	
TMP-20	5/9/2016	20	151.1	478	
TMP-20	5/9/2016	40	219.7	458	
TMP-20	5/9/2016	60	241.0	438	
TMP-20	5/9/2016	80	254.3	418	
TMP-20	5/9/2016	100	265.0	398	
TMP-20	5/9/2016	120	271.7	378	
TMP-20	5/9/2016	140	272.8	358	
TMP-20	5/18/2016	20	151.2	478	
TMP-20	5/18/2016	40	220.8	458	
TMP-20	5/18/2016	60	241.8	438	
TMP-20	5/18/2016	80	255.0	418	
TMP-20	5/18/2016	100	265.6	398	
TMP-20	5/18/2016	120	272.4	378	
TMP-20	5/18/2016	140	273.9	358	
TMP-20	5/23/2016	20	152.5	478	
TMP-20	5/23/2016	40	221.8	458	
TMP-20	5/23/2016	60	243.1	438	
TMP-20	5/23/2016	80	256.3	418	
TMP-20	5/23/2016	100	266.7	398	
TMP-20	5/23/2016	120	273.3	378	
TMP-20	5/23/2016	140	275.0	358	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-10-9N	4/26/2016	20	152.4	475	
TMP-10-9N	4/26/2016	40	159.2	455	
TMP-10-9N	4/26/2016	60	157.7	435	
TMP-10-9N	4/26/2016	80	154.2	415	
TMP-10-9N	4/26/2016	100	169.1	395	
TMP-10-9N	5/2/2016	20	151.7	475	
TMP-10-9N	5/2/2016	40	158.6	455	
TMP-10-9N	5/2/2016	60	157.5	435	
TMP-10-9N	5/2/2016	80	154.1	415	
TMP-10-9N	5/2/2016	100	169.0	395	
TMP-10-9N	5/9/2016	20	150.9	475	
TMP-10-9N	5/9/2016	40	158.1	455	
TMP-10-9N	5/9/2016	60	157.7	435	
TMP-10-9N	5/9/2016	80	154.4	415	
TMP-10-9N	5/9/2016	100	168.8	395	
TMP-10-9N	5/18/2016	20	150.6	475	
TMP-10-9N	5/18/2016	40	157.8	455	
TMP-10-9N	5/18/2016	60	157.6	435	
TMP-10-9N	5/18/2016	80	154.8	415	
TMP-10-9N	5/18/2016	100	169.2	395	
TMP-10-9N	5/23/2016	20	151.2	475	
TMP-10-9N	5/23/2016	40	158.5	455	
TMP-10-9N	5/23/2016	60	158.1	435	
TMP-10-9N	5/23/2016	80	155.5	415	
TMP-10-9N	5/23/2016	100	169.5	395	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-10-9S	4/26/2016	20	155.8	476	
TMP-10-9S	4/26/2016	40	211.0	456	
TMP-10-9S	4/26/2016	60	228.0	436	
TMP-10-9S	4/26/2016	80	233.8	416	
TMP-10-9S	4/26/2016	100	247.0	396	
TMP-10-9S	5/2/2016	20	154.3	476	
TMP-10-9S	5/2/2016	40	210.2	456	
TMP-10-9S	5/2/2016	60	226.9	436	
TMP-10-9S	5/2/2016	80	232.2	416	
TMP-10-9S	5/2/2016	100	245.6	396	
TMP-10-9S	5/9/2016	20	153.5	476	
TMP-10-9S	5/9/2016	40	208.7	456	
TMP-10-9S	5/9/2016	60	226.1	436	
TMP-10-9S	5/9/2016	80	231.6	416	
TMP-10-9S	5/9/2016	100	244.8	396	
TMP-10-9S	5/18/2016	20	152.3	476	
TMP-10-9S	5/18/2016	40	206.3	456	
TMP-10-9S	5/18/2016	60	224.6	436	
TMP-10-9S	5/18/2016	80	230.5	416	
TMP-10-9S	5/18/2016	100	244.1	396	
TMP-10-9S	5/23/2016	20	152.6	476	
TMP-10-9S	5/23/2016	40	205.8	456	
TMP-10-9S	5/23/2016	60	224.4	436	
TMP-10-9S	5/23/2016	80	230.4	416	
TMP-10-9S	5/23/2016	100	243.9	396	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-10-5N	4/26/2016	20	135.4	478	
TMP-10-5N	4/26/2016	40	120.4	458	
TMP-10-5N	4/26/2016	60	114.1	438	
TMP-10-5N	4/26/2016	80	104.1	418	
TMP-10-5N	4/26/2016	100	101.9	398	
TMP-10-5N	5/2/2016	20	133.9	478	
TMP-10-5N	5/2/2016	40	120.1	458	
TMP-10-5N	5/2/2016	60	114.3	438	
TMP-10-5N	5/2/2016	80	103.6	418	
TMP-10-5N	5/2/2016	100	100.3	398	
TMP-10-5N	5/9/2016	20	132.9	478	
TMP-10-5N	5/9/2016	40	119.4	458	
TMP-10-5N	5/9/2016	60	113.8	438	
TMP-10-5N	5/9/2016	80	103.4	418	
TMP-10-5N	5/9/2016	100	100.5	398	
TMP-10-5N	5/18/2016	20	132.4	478	
TMP-10-5N	5/18/2016	40	120.6	458	
TMP-10-5N	5/18/2016	60	113.3	438	
TMP-10-5N	5/18/2016	80	101.4	418	
TMP-10-5N	5/18/2016	100	96.7	398	
TMP-10-5N	5/23/2016	20	132.2	478	
TMP-10-5N	5/23/2016	40	121.8	458	
TMP-10-5N	5/23/2016	60	114.3	438	
TMP-10-5N	5/23/2016	80	103.7	418	
TMP-10-5N	5/23/2016	100	100.0	398	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-10-5S	4/26/2016	20	141.8	477	
TMP-10-5S	4/26/2016	40	185.5	457	
TMP-10-5S	4/26/2016	60	201.4	437	
TMP-10-5S	4/26/2016	80	213.4	417	
TMP-10-5S	4/26/2016	100	227.2	397	
TMP-10-5S	5/2/2016	20	141.6	477	
TMP-10-5S	5/2/2016	40	184.3	457	
TMP-10-5S	5/2/2016	60	200.7	437	
TMP-10-5S	5/2/2016	80	212.4	417	
TMP-10-5S	5/2/2016	100	226.1	397	
TMP-10-5S	5/9/2016	20	141.0	477	
TMP-10-5S	5/9/2016	40	183.2	457	
TMP-10-5S	5/9/2016	60	200.0	437	
TMP-10-5S	5/9/2016	80	211.9	417	
TMP-10-5S	5/9/2016	100	225.3	397	
TMP-10-5S	5/18/2016	20	139.9	477	
TMP-10-5S	5/18/2016	40	181.9	457	
TMP-10-5S	5/18/2016	60	198.6	437	
TMP-10-5S	5/18/2016	80	210.4	417	
TMP-10-5S	5/18/2016	100	224.0	397	
TMP-10-5S	5/23/2016	20	140.6	477	
TMP-10-5S	5/23/2016	40	182.8	457	
TMP-10-5S	5/23/2016	60	199.0	437	
TMP-10-5S	5/23/2016	80	210.7	417	
TMP-10-5S	5/23/2016	100	224.0	397	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-5-9N	4/26/2016	20	118.6	476	
TMP-5-9N	4/26/2016	40	159.2	456	
TMP-5-9N	4/26/2016	60	156.1	436	
TMP-5-9N	4/26/2016	80	257.6	416	
TMP-5-9N	4/26/2016	100	267.3	396	
TMP-5-9N	5/2/2016	20	118.4	476	
TMP-5-9N	5/2/2016	40	159.4	456	
TMP-5-9N	5/2/2016	60	156.8	436	
TMP-5-9N	5/2/2016	80	257.2	416	
TMP-5-9N	5/2/2016	100	266.8	396	
TMP-5-9N	5/9/2016	20	118.2	476	
TMP-5-9N	5/9/2016	40	159.7	456	
TMP-5-9N	5/9/2016	60	157.4	436	
TMP-5-9N	5/9/2016	80	256.9	416	
TMP-5-9N	5/9/2016	100	266.4	396	
TMP-5-9N	5/18/2016	20	118.1	476	
TMP-5-9N	5/18/2016	40	159.2	456	
TMP-5-9N	5/18/2016	60	157.5	436	
TMP-5-9N	5/18/2016	80	256.7	416	
TMP-5-9N	5/18/2016	100	266.1	396	
TMP-5-9N	5/23/2016	20	117.3	476	
TMP-5-9N	5/23/2016	40	158.5	456	
TMP-5-9N	5/23/2016	60	157.1	436	
TMP-5-9N	5/23/2016	80	256.5	416	
TMP-5-9N	5/23/2016	100	265.9	396	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-5-9S	4/26/2016	20	146.0	476	
TMP-5-9S	4/26/2016	40	223.1	456	
TMP-5-9S	4/26/2016	60	231.2	436	
TMP-5-9S	4/26/2016	80	256.7	416	
TMP-5-9S	4/26/2016	100	268.5	396	
TMP-5-9S	5/2/2016	20	145.1	476	
TMP-5-9S	5/2/2016	40	220.8	456	
TMP-5-9S	5/2/2016	60	229.0	436	
TMP-5-9S	5/2/2016	80	256.2	416	
TMP-5-9S	5/2/2016	100	267.9	396	
TMP-5-9S	5/9/2016	20	145.0	476	
TMP-5-9S	5/9/2016	40	222.0	456	
TMP-5-9S	5/9/2016	60	230.5	436	
TMP-5-9S	5/9/2016	80	256.0	416	
TMP-5-9S	5/9/2016	100	267.8	396	
TMP-5-9S	5/18/2016	20	144.7	476	
TMP-5-9S	5/18/2016	40	223.3	456	
TMP-5-9S	5/18/2016	60	231.9	436	
TMP-5-9S	5/18/2016	80	256.1	416	
TMP-5-9S	5/18/2016	100	267.7	396	
TMP-5-9S	5/23/2016	20	143.3	476	
TMP-5-9S	5/23/2016	40	224.2	456	
TMP-5-9S	5/23/2016	60	232.0	436	
TMP-5-9S	5/23/2016	80	256.1	416	
TMP-5-9S	5/23/2016	100	268.0	396	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-5-5N	4/26/2016	20	101.4	475	
TMP-5-5N	4/26/2016	40	108.7	455	
TMP-5-5N	4/26/2016	60	97.8	435	
TMP-5-5N	4/26/2016	80	256.2	415	
TMP-5-5N	5/2/2016	20	103.6	475	
TMP-5-5N	5/2/2016	40	106.7	455	
TMP-5-5N	5/2/2016	60	94.0	435	
TMP-5-5N	5/2/2016	80	255.2	415	
TMP-5-5N	5/9/2016	20	105.3	475	
TMP-5-5N	5/9/2016	40	107.7	455	
TMP-5-5N	5/9/2016	60	97.3	435	
TMP-5-5N	5/9/2016	80	255.3	415	
TMP-5-5N	5/18/2016	20	102.5	475	
TMP-5-5N	5/18/2016	40	103.6	455	
TMP-5-5N	5/18/2016	60	89.5	435	
TMP-5-5N	5/18/2016	80	255.1	415	
TMP-5-5N	5/23/2016	20	100.2	475	
TMP-5-5N	5/23/2016	40	107.4	455	
TMP-5-5N	5/23/2016	60	93.2	435	
TMP-5-5N	5/23/2016	80	255.3	415	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-5-5S	4/26/2016	20	143.2	474	
TMP-5-5S	4/26/2016	40	217.5	454	
TMP-5-5S	4/26/2016	60	240.0	434	
TMP-5-5S	4/26/2016	80	257.8	414	
TMP-5-5S	4/26/2016	100	268.5	394	
TMP-5-5S	5/2/2016	20	142.9	474	
TMP-5-5S	5/2/2016	40	216.0	454	
TMP-5-5S	5/2/2016	60	239.3	434	
TMP-5-5S	5/2/2016	80	257.3	414	
TMP-5-5S	5/2/2016	100	268.0	394	
TMP-5-5S	5/9/2016	20	142.9	474	
TMP-5-5S	5/9/2016	40	216.6	454	
TMP-5-5S	5/9/2016	60	239.5	434	
TMP-5-5S	5/9/2016	80	256.9	414	
TMP-5-5S	5/18/2016	20	142.4	474	
TMP-5-5S	5/18/2016	40	215.9	454	
TMP-5-5S	5/18/2016	60	239.2	434	
TMP-5-5S	5/18/2016	80	257.0	414	
TMP-5-5S	5/23/2016	20	142.9	474	
TMP-5-5S	5/23/2016	40	216.1	454	
TMP-5-5S	5/23/2016	60	239.2	434	
TMP-5-5S	5/23/2016	80	256.8	414	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-31	4/26/2016	20	211.6	474	
TMP-31	4/26/2016	40	231.5	454	
TMP-31	4/26/2016	60	247.6	434	
TMP-31	4/26/2016	80	265.0	414	
TMP-31	4/26/2016	100	272.8	394	
TMP-31	4/26/2016	120	279.4	374	
TMP-31	4/26/2016	140	283.1	354	
TMP-31	4/26/2016	160	257.9	334	
TMP-31	4/26/2016	193	159.9	301	
TMP-31	5/2/2016	20	212.0	474	
TMP-31	5/2/2016	40	231.5	454	
TMP-31	5/2/2016	60	247.3	434	
TMP-31	5/2/2016	80	264.7	414	
TMP-31	5/2/2016	100	272.5	394	
TMP-31	5/2/2016	120	279.4	374	
TMP-31	5/2/2016	140	283.0	354	
TMP-31	5/2/2016	160	258.4	334	
TMP-31	5/2/2016	193	159.6	301	
TMP-31	5/9/2016	20	211.0	474	
TMP-31	5/9/2016	40	231.0	454	
TMP-31	5/9/2016	60	246.8	434	
TMP-31	5/9/2016	80	264.1	414	
TMP-31	5/9/2016	100	272.1	394	
TMP-31	5/9/2016	120	278.9	374	
TMP-31	5/9/2016	140	282.6	354	
TMP-31	5/9/2016	160	258.7	334	
TMP-31	5/9/2016	193	159.6	301	
TMP-31	5/18/2016	20	211.5	474	
TMP-31	5/18/2016	40	232.2	454	
TMP-31	5/18/2016	60	247.4	434	
TMP-31	5/18/2016	80	264.8	414	
TMP-31	5/18/2016	100	272.7	394	
TMP-31	5/18/2016	120	279.0	374	
TMP-31	5/18/2016	140	282.6	354	
TMP-31	5/18/2016	160	259.6	334	
TMP-31	5/18/2016	193	159.4	301	
TMP-31	5/23/2016	20	212.0	474	
TMP-31	5/23/2016	40	232.7	454	
TMP-31	5/23/2016	60	248.1	434	
TMP-31	5/23/2016	80	265.1	414	
TMP-31	5/23/2016	100	273.2	394	
TMP-31	5/23/2016	120	280.1	374	
TMP-31	5/23/2016	140	283.9	354	
TMP-31	5/23/2016	160	261.0	334	
TMP-31	5/23/2016	193	161.3	301	

TMP_ID	READ_DATE	DEPTH	READING	ELEVATION	Comments
TMP-32	4/26/2016	20	200.4	484	
TMP-32	4/26/2016	40	225.7	464	Reading was intially entered with transcription error as 255.7 - checked by FEI and corrected
TMP-32	4/26/2016	60	245.8	444	
TMP-32	4/26/2016	80	259.7	424	
TMP-32	4/26/2016	100	271.0	404	
TMP-32	4/26/2016	120	278.2	384	
TMP-32	4/26/2016	140	280.2	364	
TMP-32	4/26/2016	160	283.9	344	
TMP-32	4/26/2016	180	283.3	324	
TMP-32	4/26/2016	200	234.3	304	The resistivity has flucuated week to week.
TMP-32	5/2/2016	20	200.1	484	
TMP-32	5/2/2016	40	225.5	464	Reading was intially entered with transcription error as 255.7 - checked by FEI and corrected
TMP-32	5/2/2016	60	245.6	444	
TMP-32	5/2/2016	80	259.4	424	
TMP-32	5/2/2016	100	270.3	404	
TMP-32	5/2/2016	120	277.5	384	
TMP-32	5/2/2016	140	279.9	364	
TMP-32	5/2/2016	160	283.7	344	
TMP-32	5/2/2016	180	283.2	324	
TMP-32	5/2/2016	200	234.4	304	The resistivity has flucuated week to week.
TMP-32	5/9/2016	20	199.8	484	
TMP-32	5/9/2016	40	225.1	464	Reading was intially entered with transcription error as 255.7 - checked by FEI and corrected
TMP-32	5/9/2016	60	245.3	444	
TMP-32	5/9/2016	80	259.0	424	
TMP-32	5/9/2016	100	270.6	404	
TMP-32	5/9/2016	120	277.4	384	
TMP-32	5/9/2016	140	279.7	364	
TMP-32	5/9/2016	160	283.7	344	
TMP-32	5/9/2016	180	283.2	324	
TMP-32	5/9/2016	200	234.8	304	The resistivity has flucuated week to week.
TMP-32	5/18/2016	20	201.1	484	
TMP-32	5/18/2016	40	226.5	464	
TMP-32	5/18/2016	60	246.7	444	
TMP-32	5/18/2016	80	260.8	424	
TMP-32	5/18/2016	100	272.2	404	
TMP-32	5/18/2016	120	278.9	384	
TMP-32	5/18/2016	140	282.0	364	
TMP-32	5/18/2016	160	286.3	344	
TMP-32	5/18/2016	180	285.9	324	
TMP-32	5/18/2016	200	237.7	304	The resistivity has flucuated week to week.
TMP-32	5/23/2016	20	201.6	484	
TMP-32	5/23/2016	40	226.7	464	
TMP-32	5/23/2016	60	246.9	444	
TMP-32	5/23/2016	80	260.8	424	
TMP-32	5/23/2016	100	272.3	404	
TMP-32	5/23/2016	120	278.9	384	
TMP-32	5/23/2016	140	281.6	364	
TMP-32	5/23/2016	160	286.0	344	
TMP-32	5/23/2016	180	286.1	324	
TMP-32	5/23/2016	200	238.8	304	The resistivity has flucuated week to week.