# **Bridgeton Landfill, LLC**

# **Weekly Data Submittals**

Required by Section 52.F of Agreed Order, Case No. 13SL-CC01088 Effective May 13, 2013

#### **Contents**:

**Attachment A – Leachate Levels in Leachate Collection Sumps** 

**Attachment B – Temperature Monitoring Probe Analytical Charts** 

Attachment C – Gas Interceptor Wellhead Temperature Graphs

#### **Provided Separately:**

- Leachate Level in Leachate Collection Sump Raw Data Excel Spreadsheet
- Temperature Monitoring Probe Raw Data Excel Spreadsheet
- Gas Interceptor Well Reading Raw Data Excel Spreadsheet

#### **Commentary on Data**

#### Attachment A – Leachate Levels in Leachate Collection Sumps

LCS -1,-2,-3D -5, -6 were operational during the weekly reporting period.

LCS-4B still exhibits excess pressure and liquid ejection, so it has not been fitted with a pump; however, the conditions are resulting in leachate removal from that location. Options for pumping from this location are currently under review.

Measurement devices are currently being evaluated for use in LCS-3D and -1.

#### **Temperature Monitoring Probe Analytical Charts**

The following TMPs indicated consistent or lower temperature profiles than previous week(s): TMP-1,-2,-3,-4,-5,-6,-8, -9, -10,-11 and -14.

TMP-12 measured a slight increase at shallow distances from the ground surface.


TMP-7 and -13 have been removed from the presentation based on unreliable thermocouple measurements.

#### **Gas Interceptor Wellhead Temperature Graphs**


The fluctuation in wellhead gas temperatures can be attributed to variation in available vacuum, gas flow and ambient temperatures at the respective well.

All gas interceptor wells remained relatively consistent or lower with regards to gas wellhead temperature measured at each location.


The water circulation cooling loop is currently installed in GIW-4. The cooling loop was operational during the reporting period.




#### **LCS-2D Liquid Level Above Quarry Floor**




#### **LCS-5A Liquid Level Above Quarry Floor**




#### **LCS-6B Liquid Level Above Quarry Floor**




**LCS-3D Liquid Level** 






TMP-1




TEMPERATURE VS DEPTH BRIDGETON LANDFILL


**TMP-2** 




**TMP-3** 




**TMP-4** 




**TMP-5** 




**TMP-6** 




**TMP-8** 




**TMP-9** 




**TMP-10** 




# **TMP-11**



### **TMP-12**




**TMP-14** 




TEMPERATURE VS DEPTH BRIDGETON LANDFILL


# 05/07/2014 - DEPTH



# 05/07/2014 - ELEVATION



# **AVERAGE TEMPERATURES**




1. From 5/22 - 6/12/13, only the TMP-8 reading at 20' depth was operational.

No valid readings were obtained for TMP-8 from 8/1 to 10/10/2013. Valid readings from 20' to 40' resumed on 10/16/2013.

- 2. A new OMEGA dial was installed at TMP-7R on 6/12/2013 enabling more vaild readings.
- 3. No valid readings were obtained for TMP-10 and TMP-12 on 7/18/2013 or 7/25/2013.
- 4. End terminals were replaced just prior to the 8/6/2013 readings with type T Omega connectors (part # SMPW-CC-T-M) on all TMPs except for TMP-8.

TEMPERATURE VS TIME BRIDGETON LANDFILL

# **MAXIMUM TEMPERATURES**



From 5/22 - 6/12/13, only the TMP-8 reading at 20' depth was operational.
 No valid readings were obtained for TMP-8 from 8/1 to 10/10/2013. Valid readings from 20' to 40' resumed on 10/16/2013.

2. A new OMEGA dial was installed at TMP-7R on 6/12/2013 enabling more vaild readings.

3. No valid readings were obtained for TMP-10 and TMP-12 on 7/18/2013 or 7/25/2013.

4. End terminals were replaced just prior to the 8/6/2013 readings with type T Omega connectors (part # SMPW-CC-T-M) on all TMPs except for TMP-8.

TEMPERATURE VS TIME BRIDGETON LANDFILL

