

BRIDGETON SANITARY LANDFILL  
DAILY AIR MONITORING RESULTS

Date/Time	Sample Location	H2S ppm	Benzene ppm	Odor Dillution	Comments and Odor Desc	Site Name
6/2/2013 14:00	N	0.00169	0.00	2.00	No Landfill Odor	Eise Park
6/2/2013 14:09	I	0.00000	0.00	2.00	Very Slight Landfill Odor	3719 Pennridge
6/2/2013 14:15	H	0.00000	0.00	2.00	Light Landfill Odor	Turner
6/2/2013 14:21	G	0.00000	0.00	2.00	Light Landfill Odor	Materialogic
6/2/2013 14:28	M	0.00000	0.00	2.00	Light Landfill Odor	Forshaw Parking Lot
6/2/2013 14:35	F	0.00000	0.00	2.00	No Landfill Odor	Ram's
6/2/2013 14:45	J	0.00000	0.00	2.00	No Landfill Odor	12755 St. Charles Rock Road
6/2/2013 14:51	L	0.00000	0.00	2.00	No Landfill Odor	MDNR Trailer
6/2/2013 14:59	K	0.00000	0.00	2.00	No Landfill Odor	NW Auto Body
6/2/2013 15:05	A	0.00000	0.00	2.00	No Landfill Odor	Metro Paving
6/2/2013 15:12	B	0.00000	0.00	2.00	No Landfill Odor	Jimmy John's
6/2/2013 15:21	C	0.00000	0.00	2.00	No Landfill Odor	AAA Trucking
6/3/2013 8:09	N	0.00126	0.00	2.00	No Landfill Odor	Eise Park
6/3/2013 8:22	I	0.00378	0.00	2.00	No Landfill Odor	3719 Pennridge
6/3/2013 8:29	H	0.00456	0.00	2.00	Light Landfill Odor	Turner
6/3/2013 8:35	G	0.00397	0.00	2.00	No Landfill Odor	Materialogic
6/3/2013 8:42	M	0.00442	0.00	2.00	Very Slight Landfill Odor	Forshaw Parking Lot
6/3/2013 8:49	F	0.00453	0.00	2.00	No Landfill Odor	Ram's
6/3/2013 9:01	J	0.00469	0.00	2.00	No Landfill Odor	12755 St. Charles Rock Road
6/3/2013 9:09	C	0.00446	0.00	2.00	No Landfill Odor	AAA Trucking
6/3/2013 9:16	B	0.00488	0.00	2.00	No Landfill Odor	Jimmy John's
6/3/2013 9:22	A	0.00457	0.00	2.00	No Landfill Odor	Metro Paving
6/3/2013 9:28	K	0.00464	0.00	2.00	No Landfill Odor	NW Auto Body
6/3/2013 9:34	L	0.00402	0.00	2.00	No Landfill Odor	MDNR Trailer
6/3/2013 9:43		0.00532	0.00	2.00	Light Landfill Odor	Quik Trip
6/3/2013 9:48		0.00639	0.00	2.00	Medium Landfill Odor	Intersection of Corporate Exchange and Boenker
6/3/2013 9:53		0.00553	0.00	2.00	Light Landfill Odor	Forshaw Parking Lot
6/3/2013 10:02		0.00505	0.00	2.00	No Landfill Odor	3501 San Clemente
6/3/2013 10:08		0.00501	0.00	2.00	No Landfill Odor	Spanish Village Park
6/3/2013 10:12		0.00492	0.05	2.00	No Landfill Odor	12749 San Clemente
6/3/2013 10:16		0.00502	0.05	2.00	No Landfill Odor	380 Tortosa
6/3/2013 10:21		0.00550	0.05	2.00	Light Landfill Odor	3512 El Ferrol
6/3/2013 10:35		0.00558	0.05	2.00	Light Landfill Odor	F-R Service Co.
6/3/2013 10:40		0.00427	0.05	2.00	Light Landfill Odor	Materialogic
6/3/2013 10:48		0.00430	0.00	2.00	Light Landfill Odor	Forshaw Parking Lot
6/3/2013 10:59		0.00560	0.05	2.00	Very Slight Landfill Odor	12755 St. Charles Rock Road
6/3/2013 11:06		0.00508	0.05	2.00	No Landfill Odor	Metro Paving
6/3/2013 11:20		0.00553	0.00	2.00	No Landfill Odor	12769 Spanish Village Drive
6/3/2013 11:24		0.00514	0.00	2.00	No Landfill Odor	3377 San Sevilla

BRIDGETON SANITARY LANDFILL  
DAILY AIR MONITORING RESULTS

Date/Time	Sample Location	H2S ppm	Benzene ppm	Odor Dillution	Comments and Odor Desc	Site Name
6/3/2013 11:29		0.00532	0.00	2.00	No Landfill Odor	12715 El Ferrol
6/3/2013 11:53		0.00130	0.00	2.00	Light Landfill Odor	F-R Service Co.
6/3/2013 11:58		0.00433	0.00	4.00	Medium Landfill Odor	Materialogic
6/3/2013 12:02		0.00488	0.00	4.00	Medium Landfill Odor	Intersection of Corporate Exchange and Boenker
6/3/2013 12:05		0.00451	0.00	2.00	Light Landfill Odor	Forshaw Parking Lot
6/3/2013 12:09		0.00494	0.00	2.00	No Landfill Odor	Progressive Car Insurance
6/3/2013 12:14		0.00532	0.00	2.00	Light Landfill Odor	Courtyard Marriott
6/3/2013 12:18		0.00533	0.00	2.00	Very Slight Landfill Odor	12730 San Clemente
6/3/2013 12:23		0.00554	0.00	2.00	Light Landfill Odor	Turner Farm